



PECO NUCLEAR

A Unit of PECO Energy

Robert W. Boyce
Plant Manager
Limerick Generating Station

PECO Energy Company
Limerick Generating Station
PO Box 2300
Sanatoga, PA 19464-0920
610 718 2000

10CFR50.73

April 19, 1996
Docket Nos. 50-352
50-353
License Nos. NPF-39
NPF-85

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

SUBJECT: Licensee Event Report
Limerick Generating Station - Units 1 and 2

This LER reports multiple instances of the loss of the safety function of the Control Room Emergency Fresh Air System (CREFAS) resulting in operating conditions prohibited by Technical Specifications. In addition, the automatic start feature of the back up CREFAS subsystem was not always available during these events resulting in operation outside of the design basis.

Reference:	Docket Nos. 50-352 50-353
Report Number:	1-96-006
Revision Number:	02
Event Dates:	August 26, 1984 June 22, 1989 February 07, 1996 February 18, 1996 February 23, 1996 February 28, 1996
Report Date:	April 19, 1996
Facility:	Limerick Generating Station P.O. Box 2300, Sanatoga, PA 19464-2300

This LER is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(i)(B) and 10CFR50.73(a)(2)(ii)(B). This revision provides the cause and corrective actions for these events. Changes are indicated by a revision bar in the left hand margin.

Very truly yours,

Robert W. Boyce

DBN:cah

260026

cc: T. T. Martin, Administrator Region I, USNRC
N. S. Perry, USNRC Senior Resident Inspector, LGS

9604260105 960419
PDR ADOCK 05000352
S PDR

IE 22
11