



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

NOV 7 1984

PRC

Docket Nos.: STN 50-454  
and STN 50-455

MEMORANDUM FOR: The Atomic Safety and Licensing Appeal Board for Byron:  
Alan S. Rothenthal  
Dr. Reginald L. Gotchy  
Howard A. Wilber  
The Atomic Safety and Licensing Board for Byron:  
Ivan W. Smith  
Dr. Dixon Callihan  
Dr. Richard F. Cole

FROM: Thomas M. Novak, Assistant Director  
for Licensing  
Division of Licensing

SUBJECT: BYRON QUALITY ASSURANCE AND EMERGENCY PREPAREDNESS RELATED  
DOCUMENTS AND AMENDMENT TO BYRON BYPRODUCT MATERIAL LICENSE  
(BOARD NOTIFICATION 84-176)

In accordance with present NRC Procedures for Board Notifications, the following documents are being provided:

1. Letter dated September 25, 1984 from R. L. Spessard (NRC) to Cordell Reed (Commonwealth Edison) enclosing Inspection Report No. 50-454/84-45(DRS); 50-455/84-30(DRS).
2. Letter dated September 25, 1984 from T. R. Tramm (Commonwealth Edison) to James G. Keppler (NRC) requesting amendment to Byproduct Material License No. 12-05650-18.
3. Letter dated October 1, 1984 from B. J. Holt (NRC) to T. R. Tramm (Commonwealth Edison) amending the Byproduct Material License as requested in Item 2.
4. Letter dated October 2, 1984 from L. R. Gregor (NRC) to Cordell Reed (Commonwealth Edison) concerning FEMA approval of emergency preparedness.
5. Letter dated October 4, 1984 from R. L. Spessard (NRC) to Cordell Reed (Commonwealth Edison) enclosing Inspection Report No. 50-454/84-31(DRS); 50-455/84-24(DRS).


8411130203

N005

NOV 7 1984

-2-

6. Letter dated October 10, 1984 from V. I. Schlosser (NRC) to D. J. McDonald (National Board of Boiler and Pressure Vessel Inspectors) providing status of corrective actions to National Board's findings and observations (followup to Board Notification 84-165, dated October 5, 1984).
7. Letter dated October 10, 1984 from R. L. Spessard (NRC) to Cordell Reed (Commonwealth Edison) enclosing Inspection Report No. 50-454/84-69; 50-455/84-47(DRS).



Thomas M. Novak, Assistant Director  
for Licensing  
Division of Licensing

Enclosures:  
As stated

cc: EDO  
ACRS 10  
Parties to the Proceeding  
See next page

DISTRIBUTION LIST FOR BOARD NOTIFICATION

Byron Units 1&2  
Docket No. 50-454,455

Dr. A. Dixon Callihan  
Doug Cassel, Esq.  
Ms. Diane Chavez  
Dr. Richard F. Cole  
Joseph Gallo, Esq.  
Dr. Reginald L. Gotchy  
Mrs. Phillip B. Johnson  
Michael Miller, Esq.  
Ms. Pat Morrison  
Alan S. Rosenthal, Esq.  
Ivan W. Smith, Esq.  
John Streeter, Reg. III  
Dr. Bruce von Zellen  
Howard A. Wilber, Esq.  
Steven P. Zimmerman, Esq.  
Mr. Dennis L. Farrar  
Mr. William Kortier  
Atomic Safety and Licensing  
Board Panel  
Atomic Safety and Licensing  
Appeal Panel  
Docketing and Service Section  
Document Management Branch  
Mr. Edward R. Crass  
Mr. Julian Hinds  
Mr. James G. Keppler  
David C. Thomas, Esq.  
Ms. Lorraine Creek



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

ENCLOSURE 1

SEP 25 1984

Docket No. 50-454  
Docket No. 50-455

Commonwealth Edison Company  
ATTN: Mr. Cordell Reed  
Vice President  
Post Office Box 767  
Chicago, IL 60690

Gentlemen:

This refers to the special safety inspection conducted by Messrs. D. H. Danielson and J. W. Muffett of this office on June 5-7, July 23-24 and September 14, 1984, of activities of Bechtel Power Corporation concerning Byron Station, Units 1 and 2, authorized by NRC Construction Permit No. CPPR-130 and No. CPPR-131 and to the discussion of our findings with Mr. B. Shelton at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NPC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure(s) will be placed in the NRC Public Document Room unless you notify this office, by telephone, within ten days of the date of this letter and submit written application to withhold information contained therein within thirty days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1). If we do not hear from you in this regard within the specified periods noted above, a copy of this letter and the enclosed inspection report will be placed in the Public Document Room.

~~8410190077~~

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original Signed by R. L. Spessard"

R. L. Spessard, Director  
Division of Reactor Safety

Enclosure: Inspection Report  
No. 50-454/84-45(DRS); and  
No. 50-455/84-30(DRS)

cc w/encl:

D. L. Farrar, Director  
of Nuclear Licensing  
V. I. Schlosser, Project Manager  
Gunner Sorensen, Site Project  
Superintendent  
R. E. Querio, Station  
Superintendent  
DMB/Document Control Desk (RIDS)  
Resident Inspector, RIII Byron  
Resident Inspector, RIII  
Braidwood  
Phyllis Dunton, Attorney  
General's Office, Environmental  
Control Division  
D. W. Cassel, Jr., Esq.  
Diane Chavez, DAARE/SAFE  
W. Paton,  
ELD



U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-454/84-45(DRS); 50-455/84-30(DRS)

Docket No. 50-454; 50-455

Licensee: Commonwealth Edison Company  
P.O. Box 767  
Chicago, IL 60690

Facility Name: Byron Station Unit, 1 and 2

Inspection At: Bechtel Power Corporation (Bechtel), San Francisco, CA  
NRC Region III Office (RIII)

Inspection Conducted: June 5-7, July 23-24, 1984 (Bechtel)  
September 14, 1984 (RIII)

Inspectors: *[Signature]*  
D. H. Danielson

Date 9/20/84

*[Signature]*  
James W. Muffett  
J. W. Muffett

Date 9/20/84

Approved By: *[Signature]*  
D. H. Danielson, Chief  
Materials and Processes Section

Date 9/20/84

Inspection Summary

Inspection on June 5-7, July 23-24, and September 14, 1984 (Report No. 50-454/84-45(DRS); 50-455/84-30(DRS))

Areas Inspected: Special announced safety inspection to review the Bechtel Power Corporation Independent Design Review of Byron Station. The inspection involved a total of 119 inspector hours by two NRC inspectors.

Results: No items of noncompliance or deviations were identified.

~~8440190082~~

## DETAILS

### 1. Persons Contacted

#### Commonwealth Edison Company

\*\*B. R. Shelton, Project Engineer Manager

#### Bechtel Power Management (BPM)

\*John M. Amaral, Manager QA  
\*R. S. Cahn, Licensing  
\*\*C. W. Dick, Project Manager  
\*D. B. Hardie, Quality Engineer  
\*\*E. M. Hugher, Team Leader  
\*C. Jordan, Team Leader  
\*Peter Karpa, Manager, Engineering BPM  
\*R. S. Powell, Principal Engineer  
\*D. Wolfe, Project QA Engineer

The inspector also contacted and interviewed other contractor employees.

\*Denotes those attending the exit meeting interview at Bechtel on July 24, 1984.

\*\*Denotes those attending the meeting in Region III on September 14, 1984 and the meeting at Bechtel on July 24, 1984.

### 2. Byron Independent Design Review

The purpose of this special inspection was to examine the Bechtel Power Corporation (Bechtel) independent design review (IDR) of Units 1 and 2 of the Byron Station. Three systems were selected for this review: The Component Cooling Water System, Essential Service Water System, and DC Distribution System. The purpose of the IDR was to provide an assessment by an outside party of the adequacy of the design of the Byron Station by Sargent and Lundy Engineers.

#### a. Program and Procedures

The inspectors reviewed the following Bechtel documents and procedures related to the IDR. All procedures required for the IDR were contained in a Team Procedures Manual.

- . IDR Plan, Revision 0, dated May 4, 1984
- . IDR of the Byron Station, OA Program Plan, Revision 0, dated May 4, 1984
- . IDR-1, Communications, dated May 7, 1984
- . IDR-2, Review Process, dated May 9, 1984
- . IDR-3, Processing of Observations, dated May 25, 1984
- . EDP-5.34 Indoctrination/Orientation, Revision 2, dated March 28, 1978

- . EDP-4.37, Design Qualification, Revision 5, dated December 30, 1982
- . QADP-B8, Qualification of Auditors, Revision 5, dated December 27, 1982
- . QADP-B9, Orientation and Training, Revision 4, dated March 4, 1982
- . BADP-B10, Quality Action Request, Revision 1, dated February 14, 1975
- . QADP-C1, Quality Assurance Monitoring Act, Revision 1, dated March 25, 1976
- . QADP-C3, QA Work Plan Log, Revision 4, dated December 22, 1983
- . QADP-C5, Project Quality Audits, Revision 7, dated September 24, 1982
- . QADP-C11, Quality Program Document List, Revision 4, dated December 22, 1983

These procedures had a distribution that included the Project Manager, Project QA Engineer (POAE) and Group Leaders. Also, these procedures were used only to control Bechtel work during the review and they were not used to measure the Sargent & Lundy Engineers process.

b. Indoctrination and Training

The inspector evaluated the project team's compliance to the requirements for indoctrination and training of engineering personnel and for the QA auditor. This evaluation included the review of an audit report that verified that all personnel who were required to receive training had in fact been properly trained.

In addition to reviewing this audit report the inspector selected several engineering personnel and group leaders and verified that they had received the general QA and engineering indoctrination and training as well as project unique training in the IDR plan and procedures. As part of this review the inspector also verified that the POAE assigned to this project was properly trained and qualified in accordance with ANSI N45.2.23 and approved Bechtel procedural requirements.

c. Audits

The audit program included both quality assurance monitoring of design review activities as well as quality assurance audits. The inspector reviewed the following monitoring/audit documents:

- . Byron Independent Design Review Quarterly Audit Schedule dated May 17, 1984
- . Quality Audit Checklist No. 2.0, Design Control Indoctrination and Training, Revision 0, dated May 15, 1984
- . Project Audit 2.0-1, Indoctrination and Training, Audit date May-15-22, 1984
- . Work Plan and Log for the period May 1-31, 1984



Work Plan and Log for period May 31 to June 30, 1984

The inspector verified that quality assurance audits and monitoring activities were planned, scheduled, performed, reported and closed in accordance with the approved Bechtel procedures. The design verification audit that was scheduled for the week ending June 8, 1984 was postponed to the following week due to the NRC inspection.

d. Potential Observations

A number of the potential observations were reviewed. These included potential observations which had completed the resolution process as well as some which had not completed this process. The following is a list of the potential observations:

- (1) Potential Observation 8.2:
- (2) Potential Observation 8.5:
- (3) Potential Observation 8.10
- (4) Potential Observation 8.14
- (5) Potential Observation 8.16
- (6) Potential Observation 8.17
- (7) Potential Observation 8.18
- (8) Potential Observation 8.19
  
- (9) In addition to the above, a review of the Bechtel reviewer's notes yielded the the following observation:  
  
"Document EMD 023136, Revision 04, Supports 037 and 038 located at modes 326 and 328 are reported to be deleted in the body of the report, yet they are included in the stress analysis model (and results) and hanger drawings for these supports are also included in the final report.

Bechtel's approach to resolving the safety significance of these observations appeared to be to determine if in the particular instance noted whether the hardware required change. Since one of the stated purposes of the IDR was to draw broader conclusions about the design of the Byron Plant, observations and discrepancies must be judged as to whether these discrepancies are of a type which have the potential to cause hardware changes in other instances.

The observations have been reviewed and summarized in the final IDR report. The final report also contains a trending analysis which addresses the generic aspects of the observations and also discusses root causes for the observations. This final report which was submitted to the NRC on August 16, 1984, is under review by the NRC.

e. Conclusion

Bechtel's IDR effort was performed by experienced reviewers. The reviewers were doing a detailed review. The program procedures dealing with the dispositioning of the observations were functioning properly. No items of noncompliance or deviations were identified. The acceptability of the IDR effort to the NRC will be determined from NRC's review of the final report.

4. Exit Interview

The inspector met with representatives (denoted in Persons Contacted paragraph) at the conclusion of the inspection at Bechtel Offices. The inspector summarized the scope and findings of the inspections noted in this report.