DMC





P.O. BOX 5000 - CLEVELAND, OHIO 44101 - TELEPHONE (216) 622-9800 - ILLUMINATING BLDG. - 55 PUBLIC SQUARE

Serving The Best Location in the Nation

October 25, 1984

MURRAY R. EDELMAN VICE PRESIDENT NUCLEAR Mr. James G. Keppler Regional Administrator, Region III Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

> RE: Perry Nuclear Power Plant Docket Nos. 50-440; 50-441 Potential Defect in Two Piston Skirt Castings Supplied by Transamerica Delaval [RDC 101(84)]

Dear Mr. Keppler:

Our final report to you dated April 24, 1984, concerning a potential deficiency associated with heat treating of "type AN" piston skirt castings stated that two spare "type AN" pistons identified at PNPP as being potentially defective would be returned to the manufacturer. Transamerica Delaval was to inspect, stress relieve if necessary, and return the pistons; or replace them with new, properly heat treated pistons. Corrective action was anticipated to be complete by October 1984.

At this time, the two spare "type AN" pistons have been returned to Transamerica Delaval; however, due to the results of the TDI Owners Group recommendations for this component, they have been dispositioned as "scrap" and will be replaced by properly heat treated "type AE" pistons.

Corrective action will be accomplished upon receipt of "type AE" pistons for use as spares and is anticipated by December 21, 1984.

Sincer Murray R. Edelman

B411130408 B41025 PDR ADOCK 05000440 S PDR M MRE:pab cc: Mr. J. A. Grobe USNRC, Site Office

> Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

U.S. Nuclear Regulatory Commission c/o Document Management Branch Washington, D.C. 20555

Records Center, SEE-IN Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339

OCT 3 1 1984 IE27