

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA ST. NW. BUTTE 3100

ATLANTA GEORGIA 30303

JAN 24 1984

MEMORANDUM FOR: A. Herdt, Chief, Engineering Program Branch

THRU:

J. Olshinski, Director

Engineering and Operational Programs

FROM:

B. Uryc, Investigation/Allegation Coordinator

SUBJECT:

CATAMBA: FAILURE TO MAINTAIN INTERPASS TEMPERATURE ON

STAINLESS STEEL SOCKET WELDS

CASE NO:

RII-84-A-0012

The enclosed Allegation Report reflects information developed during recent interviews conducted by N. Economos and myself at Catawba in connection with the ASLB hearings. Request you review this information and initiate appropriate action to examine this matter. In addition to the inspection of the technical issue, I would recommend your inspector interview who were identified by the alleger as working on the crew that made the welds during this particular incident. Do not interview lead man or the foreman until we can locate and interview the other welders identified above in an attempt to substantiate the allegation. Should you need assistance in these interviews, we will be glad to assist.

This alleger has been provided confidentiality and every effort must be made to protect his identity. Should you require the alleger's name we will provide it at your request.

I have assigned a tracking date of February 29, 1984 in the Region II Allegation Tracking System. Please contact me if this date needs to be adjusted.

As always, your cooperation is greatly appreciated.

Enclosure: A/S

cc w/encl:

J. Y. Vorse, Director, Ol/RII

8502280678 841016 PDR BELL84-722