



34 NOV 6 AIO: 29

**Florida  
Power**  
CORPORATION

November 1, 1984  
3F1184-03

Mr. J. P. O'Reilly  
Regional Administrator, Region II  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street N.W., Suite 2900  
Atlanta, GA 30323

Subject: Crystal River Unit 3  
Docket No. 50-302  
Operating License No. DPR-72  
IE Inspection Report No. 84-14  
Supplemental Response

Dear Sir:

On June 29, 1984, Florida Power Corporation (FPC) responded to the subject Inspection Report (3F0684-17). In the Corrective Action, FPC committed to install, by October 31, 1984, an enhanced program that will be available in the Control Room which will more fully meet the requirements of IWP-6210 and IWV-6210. Because of software developmental and hardware problems, this enhanced program will not be completed until November 30, 1984.

Sincerely,

G. R. Westafer  
Manager, Nuclear Operations  
Licensing and Fuel Management

RMB/feb

8503010083 841101  
PD? ADOCK 05000302  
Q PDR

1/10 IE-01