

ENCLOSURE 1

NOTICE OF VIOLATION

Virginia Electric and Power Company  
North Anna

Docket Nos. 50-338 and 50-339  
License Nos. NPF-4 and NPF-7

The following violation was identified during an inspection conducted on July 6 - August 5, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 3.3.3.10 (3.3.3.9 - Unit 2) requires that with less than the minimum number of radioactive liquid effluent monitoring instrumentation channels operable, for reasons other than an alarm/trip setpoint less conservative than required, action 26 of Table 3.3-13 must be taken. This requires 12 hour grab samples during discharge.

Contrary to the above, with RM SW 108 inoperable during the period July 2-9, 1984, and service water being discharged to Lake Anna, the 12 hour grab samples required by action 26 of Table 3.3-13 were not obtained.

This is a Severity Level IV violation (Supplement 1).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

AUG 27 1984

Date: \_\_\_\_\_

8411140113 841018  
PDR ADOCK 05000338  
Q PDR