

ENCLOSURE 2

NOTICE OF DEVIATION

Virginia Electric and Power Company
North Anna

Docket Nos. 50-338 and 50-339
License Nos. NPF-4 and NPF-7

The following deviation was identified during an inspection conducted on July 6 - August 5, 1984.

Paragraph 11.4.2.9 of the North Anna Power Station Units 1 and 2 updated Final Safety Analysis Report discusses the service-water-discharge-to-reservoir monitor and states in part "This channel continuously monitors the service water discharge to the service water reservoir."

Contrary to the above, this channel (RM SW 109) has been inoperable since February 9, 1983, when the sample pump was isolated and tagged out.

This deviation applies to both units.

Please provide, in writing within 30 days of the date of this Notice, a description of corrective actions regarding these deviations, actions taken to avoid further deviations, and the dates when these actions were or will be completed.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

AUG 27 1984

Date: _____

8411140120 841018
PDR ADOCK 05000338
G PDR