

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
1630 Chestnut Street Tower II

January 29, 1985 85 FEB 1 P12: 42

U.S. Nuclear Regulatory Commission
Region II
ATTN: James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:


INSPECTION AND ENFORCEMENT BULLETIN 80-13 - CRACKING IN CORE SPRAY
SPARGERS - BROWNS FERRY NUCLEAR PLANT

As required by IE Bulletin 80-13 a remote visual examination of the core spray spargers was performed on Browns Ferry unit 2 during the current cycle 5 outage. The inspections were performed in accordance with Mechanical Maintenance Instruction 14.3-A and Preservice and In-Service Visual Examination Procedure N-VT-1. The inspection revealed no unacceptable indications. This inspection was performed on November 14, 1984.

To the best of my knowledge, I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


J. W. Hufham, Manager
Licensing and Regulations

cc: U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Mr. R. J. Clark
Browns Ferry Project Manager
U.S. Nuclear Regulatory Commission
7920 Norfolk Avenue
Bethesda, Maryland 20814

8503010363 850129
PDR ADOCK 05000260
G PDR