

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power and Light Company
Turkey Point Units 3 and 4

Docket Nos. 50-250 and 50-251
License Nos. DPR-31 and DPR-41

The following violation was identified during an inspection conducted on October 22-26, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.10.1 requires that records and logs of facility operation be retained for at least five years.

Contrary to the above requirement, the following operating records were not being maintained:

- a. Attachment 2 to Administrative Procedure 0103.16, the "STA Report of Plant Abnormal Occurrences" were not being controlled as plant records in the plant records vault.
- b. Appendix A to Off-Normal Operating Procedure 0208.1, the Post Trip Review forms, were not being forwarded to the plant records vault in a timely manner. On October 24, 1984, copies of Post Trip Review reports for the Unit 3 trip on April 24, 1984, and trip reports from June 1984, onward had not been filed in the Document Control records vault.

This is a Severity Level V violation (Supplement I) and applies to both units.

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: DEC 7 1984

8503060176 850131
PDR ADOCK 05000250
G PDR