

ENCLOSURE 1

NOTICE OF VIOLATION

Georgia Power Company
Hatch

Docket Nos. 50-321 and 50-366
License Nos. DPR-57 and NPF-5

The following violation was identified during an inspection conducted on November 13-16, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50.54(a)(1) requires Georgia Power Company (GPC) to implement the quality assurance program described in its Safety Analysis Report. Section 17.2.5 of GPC QA program requires that activities affecting quality be prescribed by documented instructions and procedures. The program also requires that these activities be accomplished in accordance with these instructions and procedures.

Contrary to the above, Procedure 50AC-MNT01-0, paragraph 8.5.14 requires additional instructions when the scope of work in a maintenance activity is expanded. This was not accomplished when a deficient condition was identified and corrected during performance of maintenance Work Orders 1-84-2086 and 1-84-5858.

This is a Severity Level V violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: _____

8503060392 850204
PDR ADOCK 05000321
G PDR