

142 DELARONDE STREET P.O. BOX 6008 NEW ORLEANS, LOUISIANA 70174-8008

• (504) 386-2345

October 31, 1984

W3P84-2976 Q-3-A35.07 3-A1.01.04 A4.05

Mr. John T. Collins Regional Administrator, Region IV U.S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Collins:

Subject: Waterford 3 SES

Docket No. 50-382

POTENTIALLY REPORTABLE DEFICIENCY NO. 179

LP&L (Maintenance) Welding Program Deficiencies

Extension of Report Schedule

Reference: LP&L letter W3P84-2858 dated October 17, 1984

The referenced letter provided an interim report on the subject deficiency and related that the LP&L evaluation was expected to be completed by the end of October. Review and evaluation of the welds performed by the Maintenance Department is ongoing. The determination of the safety significance of PRD-179 is contingent on the results of the evaluation which is currently rescheduled for completion by November 30 at which time our report will be submitted pursuant to 10CFR50.55(e)(3).

Very truly yours,

KW Goh

K.W. Cook

Nuclear Support & Licensing Manager

KWC: GEW: sms

cc: NRC, Director, Office of I&E

NRC, Director, Office of Management

G.W. Knighton, NRC-NRR

E.L. Blake

W.M. Stevenson

W.A. Cross

INPO Records Center (D.L. Gillispie)

JE-37 10