



GPU Nuclear Corporation
Post Office Box 480
Route 441 South
Middletown, Pennsylvania 17057-0191
717 944-7621
TELEX 84-2386
Writer's Direct Dial Number:
5211-85-2014

January 28, 1985


Dr. Thomas E. Murley
Region I, Regional Administrator
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Dear Dr. Murley:

Three Mile Island Nuclear Station Unit 1 (TMI-1)
Operating License No. DPR-50
Docket No. 50-289
Notice of Violation for Inspection 84-34

Attached to this letter is the GPUN response to Appendix A of Inspection Report 50-289/84-34, "Notice of Violation."

Sincerely,



H. D. Hukill
Director, TMI-1

SMO/HDH/spb

Attachment

cc: R. Conte

Sworn and Subscribed to
Before me this 28th day
of January, 1985.


Notary Public

CARLA JEAN BERRY, NOTARY PUBLIC
MIDDLETOWN BORO. DAUPHIN COUNTY
MY COMMISSION EXPIRES JUNE 17, 1985
Member, Pennsylvania Association of Notaries

8503060555 850221
PDR ADOCK 05000289
G PDR

RESPONSE TO NOTICE OF VIOLATION

I. CORRECTIVE STEPS TAKEN AND THE RESULTS ACHIEVED

A memorandum was issued on October 24, 1984 to all security shifts enumerating the communications systems available to the Alarm Stations and listing the methods and numbers to use to seek off-site assistance.

Quality Assurance monitored Alarm Station personnel from November 5-13, 1984. All were cognizant of the information necessary to reach off-site assistance.

The Training Department was advised of the deficiency. Lesson plans which are part of the annual security training/retraining program were revised to emphasize the communications systems available to the Alarm Station operators.

II. CORRECTIVE STEPS WHICH WILL BE TAKEN TO AVOID FURTHER VIOLATION

Security personnel will be required as part of training and annual retraining to be cognizant of communications systems available.

Specific instructions on seeking off-site assistance will be posted in the Alarm Stations at all times.

III. DATE WHEN FULL COMPLIANCE WAS ACHIEVED

On October 24, 1984, all security personnel were briefed through a memorandum on methods to seek off-site assistance.

Lesson plans revised to address the deficiency identified were incorporated into the training and annual retraining programs on January 9, 1985.

SUMMARY OF NOTICE OF VIOLATION

As a result of the inspection conducted on October 22-26, 1984, and in accordance with the revised NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

On October 23, 1984, the Alarm Station operators were unable to demonstrate the ability to request off-site assistance. The Modified Amended Physical Security Plan, Rev. 19 requires training to be conducted in accordance with the Guard Training and Qualification Plan. This plan requires all security personnel to be trained, qualified and tested to perform duties and tasks which include the ability to request off-site assistance.