

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power Corporation
Crystal River

Docket No. 50-302
License No. DPR-72

The following violation was identified during an inspection conducted on November 26-30, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50.54(a)(1) requires Florida Power Corporation (FPC) to implement the quality assurance program described or referenced in the Safety Analysis Report. Section 1.7.1.5 of FPC's QA Program requires that activities affecting quality be performed in accordance with documented instructions and procedures of a type appropriate to the circumstances.

Contrary to the above, the following examples of inadequate procedures were identified:

- a. Surveillance Procedure SP-157, Meteorological System Surveillance did not require the testing of the four equipment malfunction alarms for Meteorological Tower 2.
- b. The Quality Engineering Inspection Plan assigned to Work Request #52533 required only one sign-off for the material verification at different periods of time for parts installed on 30 safety-related circuit breakers.

This is a Severity Level V violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: DEC 21 1984

8503060626 850131
PDR ADOCK 05000302
G PDR