

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

November 13, 1984

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Attention: Ms. E. G. Adensam, Chief
Licensing Branch No. 4

Re: Catawba Nuclear Station
Docket Nos. 50-413 and 50-414

Dear Mr. Denton:

My letter of June 29, 1984 identified certain features of the Catawba Unit 1 fire protection program which would not be complete at the time of fuel loading for Unit 1. This is to advise that items 1 (SSS modifications), 2 (damage control measures and cold shutdown procedures), 5 (CO₂ fire protection for D/G 1A), 6 (fire detector installed above turbine driven auxiliary feedwater pump) and 7 (cork filler material) have been completed.

Very truly yours,



Hal B. Tucker

ROS:slb

cc: Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Palmetto Alliance
2135½ Devine Street
Columbia, South Carolina 29205

NRC Resident Inspector
Catawba Nuclear Station

Mr. Jesse L. Riley
Carolina Environmental Study Group
854 Henley Place
Charlotte, North Carolina 28207

Robert Guild, Esq.
P. O. Box 12097
Charleston, South Carolina 29412

8411150141 841113
PDR ADDCK 05000413
F PDR

13002
/10