

ENCLOSURE 1

NOTICE OF VIOLATION

Alabama Power Company
Farley 1 and 2

Docket Nos. 50-348, 364
License Nos. NPF-2, 8

The following violations were identified during an inspection conducted on July 11 - August 15, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

1. 10 CFR 50, Appendix B, Criterion II, Quality Assurance Program, as implemented by the Farley Nuclear Plant Quality Assurance Program, FSAR Section 17, requires that the quality assurance program shall provide control over activities affecting the quality of identified structures, systems and components to an extent consistent with their importance to safety.

Contrary to the above, inadequate protection and control of certain components important to safety was not exercised in that: (1) on July 25, 1984, an electrical switchgear compartment door was opened and automatically deenergized by licensee personnel without the knowledge or consent of the shift supervisor who is charged with the safe operation of the plant; (2) on July 16, 1984, a large manual valve operator was placed in an electrical cable tray on top of electrical cables while the valve was undergoing maintenance; and (3) on July 20, 1984 various electric cable tray covers were found bent, out of position, and covers not fastened to trays.

This is a Severity Level IV violation (Supplement I).

2. 10 CFR 50, Appendix B, Criterion XII "Control of Measuring and Test Equipment", as implemented by the Farley Nuclear Plant Quality Assurance Program, FSAR Chapter 17, requires that measures be established to assure that instruments used in activities affecting quality are properly calibrated and adjusted at specified intervals.

Contrary to the above, intervals for calibration of certain instruments used in safety related activities had not been specified in that on July 23, 1984, level indicators (LI-4075A and B) for the Unit 1 condensate storage tank had not been calibrated since March, 1981 and no calibration frequency was specified.

This is a Severity Level V violation (Supplement I).

8411150269 841018
PDR ADOCK 05000348
G PDR

Alabama Power Company
Farley 1 and 2

2

Docket Nos. 50-348, 364
License Nos. NPF-2, 8

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: AUG 31 1984