

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Kewaunee Nuclear Power Plant	DOCKET NUMBER (2) 0 5 0 0 0 3 0 5	PAGE (3) 1 OF 0 2
--	---	-----------------------------

TITLE (4)
Lack of Seismic Analysis for Containment Penetration Attachment

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)
									N/A			0 5 0 0 0
0 1	2 5	8 5	8 5	0 0 2	0 0	0 2	2 4	8 5				0 5 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

OPERATING MODE (9) N	20.402(b)	20.406(c)	50.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10) 1 0 0	20.406(a)(1)(i)	50.36(e)(1)	50.73(a)(2)(v)	73.71(c)
	20.406(a)(1)(ii)	50.36(e)(2)	50.73(a)(2)(vii)	<input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.406(a)(1)(iii)	50.73(a)(2)(i)	50.73(a)(2)(viii)(A)	
	20.406(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(viii)(B)	
	20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
Richard P. Pulec, Plant Technical Supervisor	4 1 4 3 8 8 - 2 5 6 0

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS

SUPPLEMENTAL REPORT EXPECTED (14)

<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
		N/A			

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single space typewritten lines) (16)

On January 25, 1985, with the plant at full power operation, Wisconsin Public Service Corporation was notified by their Architect Engineer that a seismic analysis for the non-safety-related piping section of the Containment Integrated Leak Rate Test Penetration could not be located. This was identified during the evaluation of a proposed modification. To correct this deficiency, a design change will be completed during the in-progress 1985 refueling/maintenance shutdown with a proper seismic analysis of the as-modified design.

WPSC considers this item of sufficient significance to merit reporting to the Commission within the "OTHER" category of 10 CFR 50.73.

IC224/1

8503060838 850224
PDR ADOCK 05000305
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Kewaunee Nuclear Power Plant	DOCKET NUMBER (2) 0 5 0 0 0 3 0 5	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 5	- 0 0 2	- 0 0	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 365A's) (17)

On January 25, 1985, with the plant at full power operation, Wisconsin Public Service Corporation [WPSC] was informed by Fluor Engineers Inc. [formerly Pioneer Service and Engineering, Architect-Engineer for the Kewaunee Nuclear Plant] that they were unable to locate a seismic analysis for the non-safety-related piping section (PSP) of the Containment Integrated Leak Rate Test (JM) penetration. This section is welded directly to the Safety-related [Seismic Class 1] section of the penetration (PEN). Plant design criteria required that a seismic analysis be performed on the non-seismic Class 1 piping section extending to the first structural anchor which provided a means for isolating the seismic class 1 piping. Wisconsin Public Service and Fluor consider this to be an isolated occurrence.

The lack of documentation was identified during the evaluation of a proposed modification. To correct this deficiency, the modification will be completed during the in-progress 1985 refueling/maintenance shutdown with a proper seismic analysis of the as-modified design.

WPSC considers this item to be of sufficient significance to merit reporting to the Commission within the "OTHER" category of 10 CFR 50.73.

WISCONSIN PUBLIC SERVICE CORPORATION

P.O. Box 1200, Green Bay, WI 54305



February 25, 1985

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Gentlemen:

Docket 50-305
Operating License DPR-43
Kewaunee Nuclear Power Plant
Reportable Occurrence 85-002-00

In accordance with the requirements of 10 CFR 50.73 "Licensee Event Report System", the attached Licensee Event Report for reportable occurrence 85-002-00 is being submitted.

Very truly yours,

A handwritten signature in dark ink, appearing to read "D. C. Hintz".

D. C. Hintz
Manager - Nuclear Power

JGT/js

Attach.

cc - INPO Records Center
Suite 1500, 1100 Circle 75 Parkway
Atlanta, GA 30339
Mr. Robert Nelson, NRC Resident Inspector
RR #1, Box 999, Kewaunee, WI 54216
Mr. S. A. Varga, Chief
US NRC, Washington, DC 20555
Mr. J. G. Keppler, Regional Administrator
Region III, US NRC, 799 Roosevelt Road
Glen Ellyn, IL 60137

IE22
1/1