SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764 COLUMBIA, SOUTH CAROLINA 29218

84 Movember 102; 2284

O. W. DIXON, JR. VICE PRESIDENT NUCLEAR OPERATIONS

Mr. James P. O'Reilly Regional Administrator U.S. Nuclear Regulatory Commission Suite 2900 101 Marietta Street, NW Atlanta, GA 30323

> Virgil C. Summer Nuclear Station SUBJEC'I': Docket No. 50/395 Operating License No. NPF-12 Special Report (SPR 84-015)

Dear Mr. O'Reilly:

This report is being submitted in accordance with Technical Specification 3.7.10, "Fire Rated Assemblies." The Plant entered Mode 5 on September 30, 1984, for a refueling outage.

In support of the outage, three (3) fire barriers have been inoperable for more than seven (7) days. Two (2) of these barriers (RB 303 and PA 301) were degraded to provide personnel access to the Reactor Building. The third barrier (NOZZ 602-18) is a spare containment penetration which was degraded to facilitate cable routing to various maintenance activities inside containment. Appropriate actions have been taken to maintain compliance with Technical Specifications. These fire barriers are expected to remain degraded for the duration of the outage.

Should there be any questions, please call us at your convenience.

truly yours, Dixon, Jr. 0.

HCF:OWD/lcd Attachment

cc: (see page #2)

8411160175 841102 PDR ADOCK 05000395 PDR

OFFICIAL COPY

Mr. James P. O'Reilly Special Report (SPR 84-015) November 2, 1984 Page #2

٠

cc: V. C. Summer T. C. Nichols, Jr./O. W. Dixon, Jr. E. H. Crews, Jr. E. C. Roberts W. A. Williams, Jr. D. A. Nauman Group Managers O. S. Bradham C. A. Price D. A. Lavigne J. F. Heilman C. L. Ligon (NSRC) K. E. Nodland
R. A. Stough
G. Percival
C. W. Heh!
J. B. Knotts, Jr.
I&E Washington
Document Management Branch
INPO Records Center
ANI Library
NPCF
File

. 0