

UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

May 2, 1996

Docket File

Mr. D. L. Farrar, Manager Nuclear Regulatory Services Commonwealth Edison Company Executive Towers West III 1400 Opus Flace, Suite 500 Downers Grove, IL 60515

SUBJECT: OPERATING INTERVALS BETWEEN EDDY CURRENT INSPECTIONS FOR

CIRCUMFERENTIAL CRACK INDICATIONS IN THE BRAIDWOOD, UNIT 1,

STEAM GENERATOR TUBES (TAC NO. M94111)

Dear Mr. Farrar:

We have reviewed your letters dated February 23 and April 16, 1996, in which you modified a previous commitment made in your letter dated November 16, 1995, regarding the operating interval between Braidwood, Unit 1, steam generator (SG) tube eddy current inspections (ECI). These ECIs are intended, in part, to determine whether there are indications of circumferential cracks in the roll transition zone (RTZ) at the top of the tube sheet (TTS). Your specific proposal in your letter dated April 16, 1996, was to initiate a mid-cycle Braidwood, Unit 1, SG tube inspection for circumferential crack indications no later than October 15, 1996, in contrast with your earlier commitment to conduct this ECI for circumferential crack indications at the TTS after 24 weeks of operation at a Thot temperature greater than 500 degrees Fahrenheit. In light of recent Byron, Unit 1, SG ECI data obtained during its present refueling outage, we find this proposal to modify your original commitment unacceptable. The staff's position on this issue was communicated to you in a telephone conference on April 25, 1996.

Accordingly, we fully anticipate that you will comply with your original commitment as stated in your letter dated November 16, 1995, regarding the interval between Braidwood, Unit 1, SG tube inspections for circumferential cracks, except as modified below.

In the telephone conference cited above, the staff agreed to consider a revised estimate of the actual Braidwood, Unit 1, operating time between the spring and fall 1995 SG tube inspection outages. By letter dated April 29, 1996, you revised this interval between the previous Braidwood, Unit 1, SG tube inspections from 24 weeks to 202 days. We accept this revised estimate. Based on this revised operating interval, and accounting for outage time since the fall of 1995, you estimate that the Braidwood, Unit 1, operating interval, consistent with your original commitment, will end by July 13, 1996.

NRC FILE CENTER COPY

060028

DF0110

We request that you respond on this matter, confirming your intention, within five business days of the date of this letter. If you have any questions on this matter, please contact M. D. Lynch at (301) 415-3023.

Sincerely,

Original signed by Elinor G. Adensam

Jack W. Roe, Director Division of Reactor Projects III/IV Office of Nuclear Reactor Regulation

Docket No. STN 50-456

cc w/encl: see next page

Distribution:

Docket File

PUBLIC

RDIII-2 R/F

J. Roe (JWR)

E. Adensam

R. Capra

C. Moore

D. Lynch

OGC, 0-15 B18

ACRS, T-2 E6

M. Farber, RIII

G. Dick

R. Assa

K. Karwoski

E. Sullivan

J. Strosnider

8. Sheron

A. Thadani

R. Zimmerman

L. Miller, RIII

J. Jacobson, DRS, RIII

EDO

DOCUMENT NAME: BRAID\BR94111.LTR

*See previous concurrence

To receive a copy of this document, indicate in the bea: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

	LA: AD3-2	A STATE OF THE PARTY OF THE PAR	PM: PD3-2	D:PD3-2 4	NRR:DE	LD708,DW
NAME	VC/Mbore	M. B. Lynch	R. Assa (A)	R. Capra of	*B. Sheron	I Roe
DATE	05/ 796	05/01/96	05/1/96	05/ / /96	05/1/96	05/1/96

D. L. Farrar Commonwealth Edison Company

cc:

Michael Miller, Esquire Sidley and Austin One First National Plaza Chicago, Illinois 60603

Regional Administrator U.S. NRC, Region III 801 Warrenville Road Lisle, Illinois 60532-4351

Illinois Department of Nuclear Safety Office of Nuclear Facility Safety 1035 Outer Park Drive Springfield, Illinois 62704

Document Control Desk-Licensing Commonwealth Edison Company 1400 Opus Place, Suite 400 Downers Grove, Illinois 60515

Mr. William P. Poirier
Westinghouse Electric Corporation
Energy Systems Business Unit
Post Office Box 355, Bay 236 West
Pittsburgh, Pennsylvania 15230

Joseph Gallo Gallo & Ross 1250 Eye St., N.W., Suite 302 Washington, DC 20005

Ms. Bridget Little Rorem Appleseed Coordinator 117 North Linden Street Essex, Illinois 60935

Howard A. Learner
Environmental Law and Policy
Center of the Midwest
203 North LaSalle Street
Suite 1390
Chicago, Illinois 60601

U.S. Nuclear Regulatory Commission Braidwood Resident Inspectors Office Rural Route #1, Box 79 Braceville, Illinois 60407 Braidwood Station Unit Nos. 1 and 2

Mr. Ron Stephens
Illinois Emergency Services
and Disaster Agency
110 East Adams Street
Springfield, Illinois 62706

Chairman
Will County Board of Supervisors
Will County Board Courthouse
Joliet, Illinois 60434

Ms. Lorraine Creek Rt. 1, Box 182 Manteno, Illinois 60950

Attorney General 500 South Second Street Springfield, Illinois 62701

George L. Edgar Morgan, Lewis and Bochius 1800 M Street, N.W. Washington, DC 20036

Commonwealth Edison Company Braidwood Station Manager Rt. 1, Box 84 Braceville, Illinois 60407

EIS Review Coordinator U.S. Environmental Protection Agency 77 W. Jackson Blvd. Chicago, Illinois 60604-3590