

Arizona Public Service Company

October 23, 1984
ANPP-30930-TDS/TRB

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Reactor Safety and Projects

Subject: Time Extension For Report - DER 84-40
A 50.55(e) Potentially Reportable Deficiency Relating To
Unit 2 Auxiliary Feedwater Pump Has Corrosion.
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between J. Ball and T. Bradish on
June 5, 1984
(B) ANPP-29867, dated June 29, 1984 (Interim Report)
(C) ANPP-30566, dated September 19, 1984 (Time Extension)


Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), an Interim Report was transmitted by Reference (B), and a
Time Extension was requested by Reference (C). At that time, it was
estimated that a Final Report would be available by October 24, 1984.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by November 23, 1984, at
which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Production
ANPP Project Director

EEVB/TRB/nj

cc: See Page Two

8411160556 841023
PDR ADOCK 05000529
S PDR

1/0
IE-27

Mr. T. W. Bishop
DER 84-40
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
D. B. Karner
W. E. Ide
D. B. Fasnacht
A. C. Rogers
L. A. Souza
D. E. Fowler
T. D. Shriver
C. N. Russo
J. Vorees
J. R. Bynum
J. M. Allen
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
R. P. Zimmerman
L. Clyde
M. Woods
T. J. Bloom

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339