

Appendix

NOTICE OF VIOLATION

Dow Chemical U.S.A.

Docket No. 50-264

As a result of the inspection conducted on October 24-26, 1984, and in accordance with the NRC Enforcement Policy 47 FR 9987 (March 9, 1982), the following violation was identified.

Licensee Condition 3.D.(1) states, "The Licensee shall inform the Commission of any incident or condition relating to the operation of the reactor which prevented or could have prevented a nuclear system from performing its safety function as described in the Technical Specifications. For each such occurrence, the licensee shall promptly notify by telephone or telegraph, the Director of the appropriate Atomic Energy Commission Regional Compliance Office listed in Appendix D of 10 CFR 20 and shall submit within ten (10) days a report in writing to the Director, Division of Reactor Licensing (hereinafter, Director, DRL) with a copy to the Regional Compliance Office."

Contrary to the above:

The Commission was not notified of the failure of the Log Channel (identified as one of the "Minimum Reactor Safety Circuits" by Technical Specification F.5.) on September 23, 1984, while the reactor was being operated at power.

This is a Severity Level V Violation.

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

December 10, 1984

Dated \_\_\_\_\_

*C. E. Norelius*

\_\_\_\_\_  
C. E. Norelius, Director  
Division of Reactor Projects

8412130313 841210  
PDR ADOCK 05000264  
Q PDR