APPENDIX A

MITICE OF VIOLATIONS

Jersey Central Power and Tight Company Madison Avenue at Punch Bowl Road Morristown, New Jersey 07960

Based on the results of an NRC inspection conducted on October 30 and 31, and November 5, 1975, it appears that certain of your activities were not conducted in full compliance with conditions of your NRC License No. DPR-16 as indicated below:

A. Contrary to the requirements of 10 CFR 20.203(c)(2)(111) and of Technical Specifications section 6.2.B.2, in the absence of specified control devices or positive control of each individual entry the access doors to the condenser bay, a high radiation area in which radiation levels in excess of one Rem per hour were accessible to personnel, was not maintained locked when inspected on October 31 and when reinspected on November 5, 1975.

This is an infraction.

Other items of noncompliance, identified through your internal management system and which were reported in a timely manner or corrective action was initiated, are set out in the enclosed inspection report. No additional information is needed for these items at this time.