

Docket No. 50-346

License No. NPF-3

Serial No. 1-495

January 31, 1985



RICHARD P. CROUSE  
Vice President  
Nuclear  
14191 259-5221

Mr. James C. Keppler, Regional Administrator  
Region III  
United States Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Your letter of October 1, 1984 (Log No. 1-1037), regarding the Performance Appraisal Inspection 50-346/84-19, identified specific weaknesses with the General Employee Training (GET) Program, at the Davis-Besse Nuclear Power Station, Unit No. 1.

Specifically, the Nuclear Quality Assurance Manual and AD 1807.00, Control of Conditions Adverse to Quality, place a high reliance on the ability of all employees to recognize and identify conditions adverse to quality, and this topic was not covered in the GET Program.

In Toledo Edison's letter of December 14, 1984 (Serial No. 1-488), a commitment was made to revise the GET Quality Assurance Module by February 1, 1985. Included in the revision to the module is a discussion on the philosophy of quality assurance, including an individual's responsibility to the Quality Assurance Program.

This portion was scheduled to be presented by the President and Chief Operating Officer of the Toledo Edison Company. After the module script was written and approved by the President of the Company, he became unavailable for photography and recording due to medical reasons. This has resulted in the inability to complete the revision to the module by the scheduled date.

The revised GET Quality Assurance module will be completed by February 28, 1985.

Very truly yours,

RPC:SGW:nlf  
cc: DB-1 NRC Resident Inspector

8503120411 850131  
PDR ADOCK 05000346  
Q PDR

IEOI  
FEB 4 1985 1/0