

SAFETY INSPECTION*

*THIS FORM IS BEING REVISED TO REFLECT NEW PART 20

Page 1 of 1

1. LICENSEE

Schuller International, Inc.
814 Richmond Avenue
Richmond, IN 47375

2. REGIONAL OFFICE

HEADQUARTERS, NMSS/IMNS
U.S. NUCLEAR REGULATORY COMMISSION
WASHINGTON, DC 20555

3. DOCKET NUMBER(S)

9999-0000

4. LICENSE NUMBER(S)

10 CFR 31.5
General License

5. DATE OF INSPECTION

March 27, 1996

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- ☐ 1. Within the scope of this inspection, no violations were observed.
- ☐ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- ☒ 3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a **NOTICE OF VIOLATION**, which is required to be posted in accordance with 10 CFR 19.11.
- ☐ A. _____ was not properly posted to indicate the presence of a _____ 10 CFR 20.203(b),(c),(d),(e) or 34.42.
- ☐ B. _____ of device(s) were not performed at the proper frequencies. 10 CFR _____ or License Condition Number _____.
- ☒ C. Records of installation, testing (leakage and on-off mechanism), and service were not properly maintained. 10 CFR 31.5(c)(4) or License Condition Number _____.
- ☐ D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
- ☐ E. Reports or notification of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.
- ☒ F. On March 27, 1996, labels affixed at the time of receipt to device(s) generally licensed pursuant to 10 CFR 31.5 were not maintained on the device in a legible condition. 10 CFR 31.5(c)(1)

9605140353 960426
PDR RC *
SSD-7 PDR

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE -- LICENSEE

DATE

SIGNATURE -- NRC INSPECTOR

DATE

Kent Rubright/Phillip Comstock

Douglas A. Bruch

April 25, 1996