

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

March 28, 1985

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Attention: Ms. E. G. Adensam, Chief  
Licensing Branch No. 4


Re: Catawba Nuclear Station, Unit 1  
Docket No. 50-413

Dear Mr. Denton:

License Condition 13, Anticipatory Reactor Trip, II.K.3.10, of Facility Operating License NPF-35 requires that, prior to exceeding 70% power, Duke Power Company shall complete the described turbine trip tests to verify that the PORV's will not be challenged when the anticipatory bypass is in effect.

This is to advise that the required turbine trip test was successfully conducted at 9:41 p.m. on March 27, 1985. The reactor did not trip and the PORV's were not challenged. The unit was back on-line at 11:18 p.m.

Very truly yours,



Hal B. Tucker

ROS:s1b

cc: Dr. J. Nelson Grace, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Robert Guild, Esq.  
P. O. Box 12097  
Charleston, South Carolina 29412

Palmetto Alliance  
2135½ Devine Street  
Columbia, South Carolina 29205

Mr. Jesse L. Riley  
Carolina Environmental Study Group  
854 Henley Place  
Charlotte, North Carolina 28207

NRC Resident Inspector  
Catawba Nuclear Station

8504020125 850328  
PDR ADOCK 05000413  
P PDR

AOAB  
'10