SAFETY INSPECTION

1. LICENSEE

Department of the Navy Mare Island Naval Shipyard Vallejo, California 94592 2. REGIONAL OFFICE

U. S. Nuclear Regulatory Commission 1450 Maria Lane - Suite 210 Walnut Creek, CA 94596

3. DOCKET NUMBER(S)

4 LICENSE NUMBER(S)

5. DATE OF INSPECTION

November 15-16, 1984

030-03598 04-00364-06 Licensee The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commissions (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows: 1. Within the scope of this inspection, no violations were observed. 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time. 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements. THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11. was not properly posted to indicate the presence of a . 10 CFR 20.203(b), (c), (d), (e) or 34.42. B. Containers located in _ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2). of sealed sources were not performed at the proper frequencies. 10 CFR License Condition Number D. Records of were not properly maintained. or License Condition Number 10 CFR __ E. Documents were not properly posted or otherwise made available. 10 CFR 19.11. F. Reports or notifications of ___ were not made in accordance with 10 CFR or License Condition Number 8501170259 841116 NMS LIC30 04-00364-06 PDR I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above

This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

U.S. NUCLEAR REGULATORY COMMISSION

REGION V

Report No.	84-01				
Docket No. 0	30-03598		License No.	04-00364-0	6
Licensee:	Pepartment of the Ware I slaw Vallejo, Col	e Navy 2 Naval Sh	ipyard	ory <u>1</u>	
Facility Nam	e: some	· .			
Inspection a	t: <u>Aome (f</u> onducted: <u>Nover</u>	31dg 676 - P. Radiographic B weer 15-16, 199	verly)		
Inspectors:	David 0	show		7/28/84. Date	
Approved by:	RALL	max		Date 12/12/84 8ate	
Summary: 10	cirtolair	were identify			