

PGE



Portland General Electric Company
Trojan Nuclear Plant
P.O. Box 439
Rainier, Oregon 97048
(503) 556-3713

March 27, 1984
CPY-282-84

Mr. John B. Martin
Regional Administrator - V
U. S. Nuclear Regulatory Commission
1450 Maria Lane - Suite 210
Walnut Creek, California 94596 -5368

Dear Sir:

Limiting conditions for operation (LCO) 3.7.9. of the Trojan Technical Specifications require that a special report be provided if certain fire barrier penetrations become nonfunctional and cannot be returned to functional status within seven days.

As a result of routine plant surveillance on March 21, 1984, a three-hour rated door was identified to have been nonfunctional and may have been nonfunctional for a period longer than seven days. Immediate compensatory action as specified in the LCO was taken upon discovery, which consisted of testing the operability of fire detectors and establishing an hourly fire watch patrol. The fire barrier is being evaluated for corrective action and will be restored to a functional status as soon as possible.

Sincerely,

C. P. Yundt
General Manager

CPY/JKA/SPS:pjj

c: LER Distribution
50.1a
File 93.24a (Q)

8504150131 840112
PDR ADOCK 05000344
S PDR

RECEIVED
MAR 30 1984

RECEIVED
MAR 30 1984