## SAFETY INSPECTION

			DWB COL
Pathology Laboratory, P.1  1212 Pleasant  Des Moines, IA  3. DOCKET NUMBER(S)	C. 50309	REGION III 799 ROOSEVELT GLEN ELLYN, II	
030-18333	14-20.		1/9/85
Licensee:  The inspection was an examination of the activities con Regulatory Commission's (NRC) rules and regulations a and representative records, interviews, with personnel,  1. Within the scope of this inspection, no violation  2. The inspector also verified the steps you have to those actions at this time.  3. During this inspection certain of your activities, THIS IS A NOTICE OF VIOLATION which is	nducted under your lice and the conditions of yo and observations by the as were observed. sken to correct the violat , as checked below, were required to be posted in	inse as they relate to radiation of license. The inspection of inspector. The findings as tions identified during the latin violation of NRC require accordance with 10 CFR 19	consisted of selective examinations of procedures a result of this inspection are as follows:  ast inspection. We have no further questions on ements.
C		License Condition Numb	f sealed sources were not performed at the proper dition Number were not properly maintained per
F. Reports or notifications of with 10 CFR  H. GM Survey meter (Light)	mt Cali	or License Condition Number Nated at	were not made in accordance
B501230526 B50 NMS LIC30 14-20390-01	)109 PDR -		
I hereby state that within 30 days the actions describe This statement of corrective actions is made in accords the NRC.  SIGNATURE - LICENSEE		Robert C	