



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

(61)

FEB 9 1983

FEB 9 1983
med

Mr. Leonard L. Webb
GSA Buildings Manager
Hyattsville Field Office
6525 Belcrest Road
Suite #1010
Hyattsville, Maryland 20782

Dear Mr. Webb:

Subject: Fire Extinguishers, Willste Building, Lease #GS-11B-20003

In September of 1982 the Lessor installed "ABC" multipurpose fire extinguishers as required by paragraph 6 of Rider #1 of the subject lease. There are a few of the "water" type extinguishers remaining which should be removed, with locations indicated in Enclosure #1 to this letter.

In addition, the special purpose fire extinguishers installed by GSA have not been inspected and their equipment history cards updated. Please see Enclosure #2 for these locations.

Your prompt response in resolving these issues will be appreciated.

Sincerely,

Robert E. Duck

Robert E. Duck, Operations Manager
Operations Section
Building and Operations Branch
Division of Facilities and
Operations Support, ADM

cc: SOakley, WPRU
BMitchum, S&H



Enclosures: As Stated

8501240265 840516
PDR FOIA
LEVY84-254 PDR

ENCLOSURE #1

OBSOLETE WATER TYPE EXTINGUISHERS

<u>FLOOR</u>	<u>LOCATION</u>
1st	1. By Guard Desk 2. By Rear Stairway, Room #140
2nd	1. By Water Fountain 2. By Rear Stairwell
3rd	1. By Water Fountain 2. By Rear Stairwell
4th	1. By Rear Stairwell
5th	1. By Water Fountain
6th	1. By Water Fountain 2. By Rear Stairwell
7th	1. By Water Fountain

ENCLOSURE #2

SPECIAL PURPOSE EXTINGUISHERS

In Rooms 030, 495, 939, and 1129 (total of 4)

By air handlers in center halls on Floors 1 thru 12 (total of 12)