

SAFETY INSPECTION

U.S. NUCLEAR REGULATORY COMMISSION

PUBLIC

Page 1 of 2

1. LICENSEE

Bio-Technical Resources, L.P.
1035 South 7th Street
Manitowish, WI 54220

2. REGIONAL OFFICE

REGION III
U.S. NUCLEAR REGULATORY COMMISSION
801 WARRENVILLE ROAD
LISLE IL 60532-4351

3. DOCKET NUMBER(S)

030-14747

4. LICENSE NUMBER(S)

48-00673-04

5. DATE OF INSPECTION

6/24/96

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- ☐ 1. Within the scope of this inspection, no violations were observed.
- ☐ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- ☒ 3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a **NOTICE OF VIOLATION**, which is required to be posted in accordance with 10 CFR 19.11.

- ☐ A. _____ was not properly posted to indicate the presence of a _____ 10 CFR 20.203(b),(c),(d),(e) or 34.42.
- ☐ B. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ or License Condition Number _____.
- ☐ C. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____.
- ☐ D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
- ☐ E. Reports or notification of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.
- ☒ F. LC 11 states the RSO is Ronald Huss, Ph.D., Contrary to the above as of 1/96, Reinhardt Rosson has been the RSO

9607160156 960624
PDR ADOCK 03014747
C PDR

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE

DATE

SIGNATURE - NRC INSPECTOR

DATE

James L. Ellis

6-24-96

Michael M. Franco

6/24/96

SAFETY INSPECTION

JE-07

Page 2 of 2

1. LICENSEE

Bio-Technical Resources, L.P.

2. REGIONAL OFFICE

REGION III
U S NUCLEAR REGULATORY COMMISSION
801 WARRENVILLE ROAD
LISLE IL 60532-4351

3. DOCKET NUMBER(S)

030-14747

4. LICENSE NUMBER(S)

48-00673-04

5. DATE OF INSPECTION

6/24/96

☒ 3.

(Continued)

10 CFR 71.3 References

☒ G.

49 CFR 173.421 That Limited Quantity packages do not contain surface contamination in excess of 173.443(b). Continuing to the above on 2/1/95, the licensee did not determine if surface contamination was present on a package containing 1.5 kg of C-14.

10 CFR 71.5 H. References

☒ I.

49 CFR 172.202(c) states that the shipping description on the shipping paper must include the proper shipping name prescribed for the material in column 2 of 172.101 table. Continuing to the above, the licensee did not place the proper shipping name on shipping papers of 1.5 kg (C-14) shipped on 2/1/95. LC 16: Application dated 10/24/94 stating state training may include written intensive material or video material as needed. Continuing to the above prior to 2/1/95, a research was not performed of regulations or procedures for packaging and shipping radioactive material.

4. The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.

☐ A.

☐ B.

☐ C.