


520 Medical Drive + Guymon, Oklahoma 73942 + (405) 338-6515

October 19, 1992



Regional Administrators
Division of Radiation Safety and Safeguards
United States Nuclear Regulatory Commission, Region IV
511 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

Reference:

Docket # 030-20282/92-01

License #35-23125-01

Gentlemen,

In response to your letter of October 8, 1992 requesting a description of our plans to improve the effectiveness of the management control of our licensed program, a the following plan has been initiated:

The Nuclear Medicine department shall be monitored weekly by the department director as to the completion of all requirements. Such monitoring will be documented by the director.

When these violations occurred before, the program was not monitored on a regular basis by the department supervisor. This monitoring will prevent negligence on the part of the department.

Sincerely,

Douglas K. Weaver

Chief Executive Officer

Congland Means

ib

9211030103 921019 REG4 LIC30 35-23125-01 PDR DUE (IE-0)