


Webber



2025 S. Brentwood Blvd.  
Brentwood, Missouri 63144-1833  
314-968-1642 (Brentwood)  
314-447-1642 (St. Charles)  
FAX: 314-968-3557  
October 26, 1992

Mr. Gary L. Shear  
Nuclear Materials Safety Section 2  
Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Re: License # 24-24865-01  
Docket # 030-29753

Dear Mr. Shear:

In response to your letter dated September 30, 1992, we are responding to your request for description of proposed corrective action for Violation #1.

Since the inspection conducted by Mr. Michael F. Webber of your office on September 17, 1992, we have appointed the assistant laboratory manager as the person responsible for the leak tests of the Troxler nuclear gauges. We have prepared a schedule stating the frequency of testing, which is every six months, and we will leak test all of our Troxlers at the same time. A notice was placed on the Troxler storage room door stating the date in which Troxlers are to be leak tested. After the testing, another notice will be posted with the next leak test date. As the radiation safety officer, I will see to it that these procedures are followed.

If you have any questions concerning this letter, please call.

Respectfully submitted,

BRUCKER & ASSOCIATES, LTD.

Michael R. Webber  
Radiation Safety Officer

MRW/tlk

9211160148 921104  
PDR ADOCK 03029753  
C PDR

OCT 29 1992