

ENCLOSURE 1

NOTICE OF VIOLATION

Duke Power Company  
Catawba Unit 2

Docket No. 50-414  
License No. NPF-52

During the Nuclear Regulatory Commission (NRC) inspection conducted on September 16, 1992 - October 10, 1992, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

Technical Specification 6.8.1 requires in part that written procedures be established, implemented and maintained covering the activities referenced in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978. Maintenance Procedure MP/0/A/7650/115, Erection and Removal of Scaffolding, prohibits scaffolding from being secured to piping less than three inches in diameter, prohibits scaffolding from being secured to piping with mirror insulation, requires that security/stack pins be installed in all sections, and requires that decking/planking and toeboards be secured.

Contrary to the above, MP/0/A/7650/115 was not followed on July 15, 1992, when maintenance personnel erected scaffolding in the 2A and 2B Diesel Generator rooms in that they secured scaffolding to 3/4 inch piping, secured scaffolding to piping with mirror insulation, failed to install security/stack pins in all scaffolding sections, and failed to secure certain sections of decking/planking and toeboards.

This is a Severity Level IV Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Duke Power Company is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region II, a copy to the NRC Resident Inspector, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received

Duke Power Company  
Catawba Unit 2

2

Docket No. 50-414  
License No. NPF-52

within the time specified in this Notice, an order or demand for information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Atlanta, Georgia  
this 9th day of November 1992