



April 23, 1985

DMB COPY

License #34-19007-01MD

34-15204

U.S.N.R.C.  
Region III  
799 Roosevelt Rd.  
Glen Ellen, IL 60137

ATTN: Nuclear Safety &  
Safeguards Branch

Gentlemen:

This letter is in reply to certain items of non-compliance regarding inspection report 030-15204/85-001(DRSS).

In regard to item 1: A lead shield has been constructed in the fume hood and all volatile I-131 is now stored there.

In regard to item 3: All employees were reminded of the necessity of wearing gloves and a lab coat when handling pigs. Vinyl gloves were purchased for use by employees sensitive to Latex gloves; (a common complaint) The pharmacist on duty will run spot checks to ensure compliance.

No reply was necessary for item 2.

Finally, to insure any equipment being transferred to unrestricted use is not contaminated with any radioisotopes, a survey with a Geiger-Muller meter and a wipe test will be performed. The results will be recorded in the incident log book, located in the managers desk, along with the date and name of the person performing the survey. If any activity above background is found, the equipment will be decontaminated and resurveyed. Equipment will not be released for unrestricted use until survey results are no higher than background.

If you have any questions, I can be contacted at (513) 461-9300 from 7:00 a.m. to 4:30 p.m.

Sincerely,

John McMaken, RPh  
and site RSO

8505060386 850423  
REG3 LIC30  
34-19007-01MD PDR

Syncor International Corporation  
Medical Services Group  
300 Forest Avenue  
Dayton, Ohio 45405  
(513) 461-9300

APR 29 1985

IE07  
1/0