

APR 22 1985

License No. 37-20830-01
Docket No. 030-21236
Control No. 03621

Cardiovascular Associates, Inc.
ATTN: Donald J. Belmont, M.D.
1210 S. Cedar Crest Boulevard, Suite 2300
Allentown, Pennsylvania 18103

Gentlemen:

Please find enclosed your NRC material license.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the Region I Material Licensing Section, (215) 337-5239, so that we can provide appropriate corrections and answers.

Please be advised that you must conduct your program involving licensed radioactive materials in accordance with the conditions of your NRC license, representations made in your license application, and NRC regulations. In particular, please note the items in the enclosed, "Requirements for Materials Licensees."

Thallium-201 and Cobalt-57, which is naturally occurring or produced in an accelerator is not byproduct material as defined in Section 30.4(d) of Title 10, Code of Federal Regulations, Part 30 and is not subject to licensing by the NRC. Therefore, you may procure and use it without amendment to your byproduct material license.

You should contact your State regulatory authorities to determine the State licensing or registration requirements for use of this product.

Although we have authorized Groups II and III on this license for NRC purposes please note your authorization as stated in Condition 12 and the wording of Condition 15 which restricts you to the Technetium 99m radiopharmaceuticals for cardiac imaging and diagnosis.

Since serious consequences to employees and the public can result from failure to comply with NRC requirements, the NRC expects licensees to pay meticulous attention to detail and to achieve the high standard of compliance which the NRC expects of its licensees.

You will be periodically inspected by NRC. A fee may be charged for inspections in accordance with 10 CFR Part 170. Failure to conduct your program safely and in accordance with NRC regulations, license conditions, and

OFFICIAL RECORD COPY

37-20830-01/LTR - 0001.0.0
04/16/85

8505100012 850422
REQ1 LIC30
37-20830-01 PDR

ML10

representations made in your license application and supplemental correspondence with NRC will result in prompt and vigorous enforcement action against you. This could include issuance of a notice of violation, or in case of serious violations, an imposition of a civil penalty or an order suspending, modifying or revoking your license as specified in the General Policy and Procedures for NRC Enforcement Actions, 10 CFR Part 2, Appendix C.

We wish you success in operating a safe and effective licensed program.


Sincerely,

Original Signed By
Jenny M. Johansen

Jenny M. Johansen, M.S.
Nuclear Materials Safety Section B
Division of Radiation Safety
and Safeguards

Enclosures:

1. License No. 37-20830-01
2. Requirements for Materials Licensees
3. 10 CFR Parts 2, 19, 20, 30, 35, and 170
4. Regulatory Guide 10.8

RI:DRSS
Johansen/k
4/17/85 

OFFICIAL RECORD COPY

37-20830-01/LTR - 0002.0.0
04/16/85

4/15/85

TELEPHONE OR VERBAL CONVERSATION RECORD

TIME

☐ A.M.
☐ P.M.

☐ INCOMING CALL

☐ OUTGOING CALL

☐ VISIT

PERSON CALLING

J. Johansen

OFFICE/ADDRESS

PHONE NUMBER

EXTENSION

PERSON CALLED

OFFICE/ADDRESS

PHONE NUMBER

EXTENSION

CONVERSATION

SUBJECT

Note to file 37-20830-01

SUMMARY

Since individual had some experience with Group II and had done kits in Group III John Glenn authorized me to place Groups II & III on license.

The restrictions to the radiopharmaceutical form are covered in Conditions 12 and 15 of license

The LMS system did not have codes to fit otherwise - JMJ

REFERRED TO:

37-20830-01

ACTION REQUESTED

None

"OFFICIAL RECORD COPY" ML10

☐ ADVISE ME OF ACTION TAKEN.

INITIALS

DATE

JMJ
4/15/85

ACTION TAKEN

INITIALS

DATE

BETWEEN: William O. Miller, Chief
License Fee Management Branch
Office of Administration

John E. Glenn, Chief
Nuclear Materials Section B
Division of Engineering and
Technical Programs

LICENSE FEE TRANSMITTAL

A. REGION I

1. APPLICATION ATTACHED

Applicant/Licensee:

Cardiovascular Assoc, Inc.

Application Dated:

3-13-85

Control No.:

03621

License No.:

NEW

2. FEE ATTACHED

Amount:

\$580

Check No.:

11363

3. COMMENTS

Signed

SLT

Date

4-8-85

B. LICENSE FEE MANAGEMENT BRANCH

1. Fee Category and Amount:

7C \$580

2. Correct Fee Paid. Application may be processed for:

Amendment

Renewal

License

✓

Signed

Frances Brown

Date

4/15/85

no info

CARDIOVASCULAR ASSOCIATES, INC.
1210 S. CEDAR CREST BLVD.
SUITE 2300
ALLENTOWN, PA 18103

REMITTANCE ADVICE			
Donald J Belmont MD			

60-131
313
11363

PAY Five hundred eighty and 00/100

TO THE ORDER OF	DATE	DESCRIPTION	CHECK NO.	CHECK AMOUNT
NRC	3/31/85	nure appl. fee Belmont 11363		580.00

THE MERCHANTS NATIONAL BANK
OF ALLENTOWN, ALLENTOWN, PA.

CARDIOVASCULAR ASSOCIATES, INC.

[Signature]
[Signature]

⑈011363⑈ ⑆031301312⑆ 18 58265⑈