

May 8, 1996

10 CFR Part 50
Section 50.73

US Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22


LER 96-003

During a Re-analysis of the High Energy Line Break,
An Error was found in the Existing Analysis

The Licensee Event Report for this occurrence is attached. An extension of the submittal due date to May 10, 1996 was obtained from the NRC Resident Inspector for this report. This report contains the following new NRC commitments:

Modifications will be performed such that the HELB of concern does not result in harsh environments for the 4kV switchgear, MCC-142 and MCC-143 areas.

Please contact Tom Parker at (612) 295-1014 if you require further information.



William J Hill
Plant Manager
Monticello Nuclear Generating Plant

c: Regional Administrator - III NRC
Sr Resident Inspector, NRC
NRR Project Manager, NRC
State of Minnesota, Attn: Kris Sanda

Attachment

140072

9605140492 960508
PDR ADDCK 05000263
S PDR

