



COOPERATIVE

P.O. BOX 817 • 2615 EAST AV. SOUTH • LA CROSSE, WISCONSIN 54601

PRIORITY ROUTING

(608) 788-4000

First	Second
RA	RC
DRA	ETC
DRP	SGA
DRS	HL
DRSS	OL
DRMA	ROI
	IPAC

FILE *len*

March 13, 1985

In reply, please
refer to LAC-10629

DOCKET NO. 50-409

Mr. James G. Keppler, Regional Administrator
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE
LA CROSSE BOILING WATER REACTOR (LACBWR)
PROVISIONAL OPERATING LICENSE NO. DPR-45
EMERGENCY PLAN

Dear Mr. Keppler:

In accordance with 10CFR50.54q, Dairyland Power Cooperative proposes the enclosed changes to the LACBWR Emergency Plan. The proposed changes affect Table E-1, which categorizes possible plant conditions into Emergency Action Levels.

Four conditions, which were categorized as unusual events, are being eliminated from the table. These are: (1) MSIV failure to close after steam pressure decreases to 900 psig, (2) unanticipated loss of Emergency Diesel Generator when required to be operable, (3) unanticipated loss of Diesel Building DC power supply, and (4) unanticipated loss of ESWSS when required to be operable. The guidance provided in NUREG-0654, Revision 1, does not list any of these conditions, as example unusual events.

The LACBWR Emergency Plan does include as an unusual event: "other plant conditions exist that require plant shutdown under Technical Specifications." Based on the inclusion of this criteria and that the four conditions are not listed in NUREG-0654, Revision 1, Dairyland Power Cooperative feels these conditions can be removed from the list of Emergency Action Levels without a significant degradation of the plan.

Therefore, Dairyland Power Cooperative requests that the NRC approves the proposed changes. The proposed changes have been reviewed by the LACBWR Operations Review Committee and the Safety Review Committee. The proposed revised pages are attached to this letter.

8506110129 850313
PDR ADOCK 05000409
F PDR

MAR 18 1985


Mr. James G. Keppler, Regional Administrator
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region III

March 13, 1985
LAC-10629

If there are any questions, please contact us.

Sincerely yours,

DAIRYLAND POWER COOPERATIVE

A handwritten signature in cursive script, appearing to read "Frank Linder", is written over the typed name.

Frank Linder, General Manager

FL:LSG:aes

Enclosures

CC: Resident Inspector

TABLE E-1
(Continued)

EVENT TYPE	POSSIBLE INDICATIONS	POSSIBLE PLANT CONDITIONS	EMERGENCY ACTION LEVEL		
			UNUSUAL EVENT	SITE ALERT	GENERAL EMERGENCY
System/ Equipment Failure or Malfunction (Loss of Safety System)	Emergency Core Spray Flow (Lo) Annunciator E14-1	Unanticipated complete loss of ECCS during Operating Conditions 1-3.	X		
	Alternate Core Spray System Lo Flow Annunciator E15-3				
	Fire Header Water Pressure (Lo) Annunciator B8-4.	Loss of fire protection system functions requiring shutdown by Technical Specifications.	X		
System/ Equipment Failure or Malfunction (Loss of Contain- ment Integrity)	Airlocks fail Surveillance Test	Loss of containment integrity during operation such that the Technical Specifications require Reactor Shutdown.	X		

(THIS PAGE IS INTENTIONALLY LEFT BLANK.)