



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

NOV 30 1979

Docket No. 50-358

Mr. Earl A. Borgmann
Vice President - Engineering
The Cincinnati Gas and Electric Company
P. O. Box 960
Cincinnati, Ohio 45201

Dear Mr. Borgmann:

SUBJECT: SEPARATION OF ELECTRICAL EQUIPMENT AND SYSTEMS AT NUCLEAR POWER PLANTS
(Zimmer Nuclear Power Station, Unit 1)

We would like to advise you of a letter (Enclosure 1) dated August 16, 1979 to the Office of Inspection and Enforcement from the Washington Public Power Supply System which indicates that a review of the equipment and systems installed in the control room of the WPPSS Nuclear Project No. 2 uncovered over 150 instances of violations of separation criteria.

In view of the large number of violations cited in the letter of August 16, 1979 for the control room, and the apparent ease with which they can occur anywhere in the plant, we require that you conduct a plant-wide field audit of your installed electric equipment and systems to determine conformance to your stated criteria.

Enclosure 2 specifies the procedures to be used for conducting an acceptable electrical separation field audit at your facility.

Within fifteen days of receipt of this letter, please advise us of your intent to comply with our requirements as specified in Enclosure 2.

Sincerely,

J. F. Stolz
John F. Stolz, Chief
Light Water Reactors Branch No. 1
Division of Project Management

Enclosures:

1. WPPSS Letter dated August 16, 1979
2. Separation Field Audit

cc: See next page

90013184

7 912190 534

POOR ORIGINAL

NOV 30 1979

cc: Troy B. Conner, Jr., Esq.
Conner, Moore & Corber
1747 Pennsylvania Avenue, N. W.
Washington, D. C. 20006

Mr. William J. Moran
General Counsel
The Cincinnati Gas and Electric
Company
P. O. Box 960
Cincinnati, Ohio 45201

Mr. William G. Porter, Jr.
Porter, Stanley, Arthur
and Platt
37 West Broad Street
Columbus, Ohio 43215

Mr. Steven G. Smith, Manager
Engineering & Project Control
The Dayton Power and Light
Company
P. O. Box 1247
Dayton, Ohio 45401

J. Robert Newlin, Counsel
The Dayton Power and Light
Company
P. O. Box 1247
Dayton, Ohio 45401

Mr. James D. Flynn
Manager, Licensing
Environmental Affairs
The Cincinnati Gas and
Electric Company
P. O. Box 960
Cincinnati, Ohio 45201

Mr. J. P. Fenstermaker
Senior Vice President-Operations
Columbus and Southern Ohio
Electric Company
215 North Front Street
Columbus, Ohio 43215

David Martin, Esq.
Office of the Attorney General
209 St. Clair Street
First Floor
Frankfort, Kentucky 40601

David B. Fankhauser, PhD
3569 Nine Mile Road
Cincinnati, Ohio 45230

Dr. Frank F. Hooper
School of Natural Resources
University of Michigan
Ann Arbor, Michigan 48109

Mr. Stephen Schumacher
Miami Valley Power Project
P. O. Box 252
Dayton, Ohio 45401

Ms. Augusta Prince, Chairperson
601 Stanley Avenue
Cincinnati, Ohio 45226

Charles Bechhoefer, Esq., Chairman
Atomic Safety & Licensing Board
Panel
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Glenn O. Bright
Atomic Safety and Licensing
Board Panel
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Leah S. Kosik, Esq.
3454 Cornell Place
Cincinnati, Ohio 45220

W. Peter Heile, Esq.
Assistant City Solicitor
Room 214, City Hall
Cincinnati, Ohio 45220

Atomic Safety and Licensing Board
Panel
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Atomic Safety and Licensing Appeal
Board
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

90013185



ENCLOSURE 1

Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. BOX 988

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

August 16, 1979
G02-79-145

Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1900 N. California Boulevard
Walnut Creek, California 94596



Attention: Mr. R. H. Engelken, Director

Subject: WPPSS NUCLEAR PROJECT NO. 2
DOCKET NUMBER 50-397, CPPR-93
REPORTABLE DEFICIENCY - 10CFR50.55(e)

Dear Mr. Engelken:

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on July 16, 1979, of a reportable deficiency involving Plant Electrical Separation.

Attached is our report concerning this deficiency.

Please contact us if you have any questions.

Very truly yours,

D L Renberger

D. L. RENBERGER
Assistant Director
Technology

90013186

DLR/GWB/ln

Attachment

DUPLICATE
7909110460

B019
5
1/1
460