

CONTROL BLOCK:

--	--	--	--	--	--	--

1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	P	A	B	V	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36
		LICENSEE CODE							LICENSE NUMBER												LICENSE TYPE					EXPIRATION DATE			

CON'T

0	1
7	8

REPORT SOURCE

L	8	0	5	0	0	0	3	3	4	7	0	9	2	0	7	9	3	1	2	1	9	7	0	0
60	61	DOCKET NUMBER					66	69	EVENT DATE					74	REPORT DATE					80				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 7 The plant was in Operational Mode 3 with the RCS temperature less than the 10-10
0 1 average temperature value of 543 degrees. At 1108 hours, the No. 4 Vital Bus
0 4 Inverter was transferred from its auxiliary power source to the Inverter. However,
0 5 the Inverter was not operable and, when the vital bus was transferred to the
0 6 deenergized inverter, it resulted in a high steam flow signal coincident with the
0 7 10-10 temperature and a safety injection occurred. Safety injections to date:
0 8 13 operational, 2 preoperational.

0 9		SYSTEM CODE E D 11		CAUSE CODE A 12		CAUSE SUBCODE A 13		COMPONENT CODE G E N E R A 14		COMP SUBCODE F 15		VALVE SUBCODE Z 16	
7 8		9 10		11 12		13 14		15 16		17 18		19 20	
17		LER RO REPORT NUMBER		EVENT YEAR 7 9 21		SEQUENTIAL REPORT NO. 0 4 0 24		OCCURRENCE CODE 9 9 25		REPORT TYPE X 30		REVISION NO. 0 32	
22		ACTION FUTURE ACTION		EFFECT ON PLANT C 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23		PRIME COMP SUPPLIER A 25	
23		24 25		26 27		28 29		30 31		32 33		34 35	
36		37 38		39 40		41 42		43 44		45 46		47 48	
49		50 51		52 53		54 55		56 57		58 59		60 61	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 1 The incident resulted from operator error in transferring the No. 4 Vital Bus to
1 2 the deenergized inverter. The involved personnel were reprimanded and reminded of
1 3 the necessity to adhere to written procedures.
1 4
1 5

FACILITY STATUS		N POWER		OTHER STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)	
1	5	1	0	1	0	1	0	1	0
G (38)		0 (39)		N/A		A (31)		Operational event	
ACTIVITY CONTENT		AMOUNT OF ACTIVITY (35)		LOCATION OF RELEASE (36)					
RELEASED OF RELEASE				N/A					
1	6	1	0	1	0	1	0	1	0
G (39)		2 (34)		N/A					

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	2	3	4	5	6	7	8	9	10
		0	0	0	2	2	18	N/A	

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
101010	10	N/A	POOR ORIGINAL

LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION		N/A		90002349	
TYPE	DESCRIPTION	TYPE	DESCRIPTION	TYPE	DESCRIPTION	TYPE	DESCRIPTION
1	1	2	2	3	3	4	4

PUBLICITY (45)
 ISSUED (N) (41) DESCRIPTION S/A 7912270520 NRC USE ONLY

NAME OF PREPARER J. A. Werling

PHONE 412-643-1258