NRC Form 366 (9-83)										E EVE	NT RE	PORT	(LER)		U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85							
FACILITY	NAME (1	1												Ip	OCKET NUMBER	(2)		PA	GE (3)			
Waterford 3 Steam Electric Station													0	151010	10	13181	1 0	FOIS				
TITLE (4	LELLO	114 5	000	CALLS A	1100			CUELO						-	1-1-1-	1-	13101		1013			
De	actor	Tri	n 0n	Tm	duo	rto	nt i	C1081	iro of	E Mai	n Stan	m Teo	latio	n Va	1 100							
EVI	INT DATE	(5)	p ou	LIIC	ER NUM	BER	6)	CIUSE	REF	PORT DAT	E (7)	111 130	Idiio	THER F	ACILITIES INVO	LVED	(8)					
MONTH DAY YEAR		YEAR SEQUENTIAL					REVISION	MONTH	DAY	YEAR		FACILI	TYNAM	ES	Doc	KET NUMBE	R(S)					
					NUM	ac m		NUMBER					N	/A		0 11	151010	1010	1.1			
	1.1									1.1.1				/ **		-						
015	05	8 5	8 9	-	011	17	-	00	06	04	8 5		N	/Δ		0	151010	101	1.1			
015			THIS R	EPORT	IS SUB	HITTE	D PUP	SUANT	TO THE R	EQUIREM	ENTS OF 10	CFR 8: 10	heck one o	r more of	f the following) (1	11)						
MODE (9)			20.402(b)					20.405	c)		x	50,73(a)	2)(iv)		73.71(b)							
POWER			2	20.405(e)(1)(i) 5					50.36(c)	(1)	2)(v)		73.71(c)									
(10) 01117			2	20.405(e)(1)(ii) 8					50.36(c)	(2)	2)(vii)		OTHER (Specify in Abstract									
20.405(a)(1)(iii) 5					50.73(a)	(2)())			50.73(a)	2)(vili)(A	U	-	365A)									
			2	0.405(s	(1)(Iv)				50,73(a)	(2)(8)			50.73(a)	2){viii}(8	1)							
20.408(a)(1)(v) 8					50.73(a)	(2)(iii)			50.73(s)	2)(x)		E.										
									ICENSEE	CONTACT	FOR THIS	LER (12)				-		1	1.1			
NAME																TEL	EPHONE NU	MBER				
															AREA CODE	T		1.24				
0.	D. Ha	ives.	One	rat	ions	Su	per	inter	ident						51014	4	16141	-1311	11 18			
		a series			COMP	LETE	ONE	INE FOR	EACH CO	MPONEN	T FAILURE	DESCRIBE	D IN THIS	REPORT	T (13)							
CAUSE	SYSTEM	COMP	COMPONENT		MANUFAC REPORTABL TURER TO NPRDS			NPRDS			CAUSE	SYSTEM	COMPONENT		MANUFAC- TURER		EPORTABLE					
x	SIB	11	ISIV	SIV W121515 N		N						1										
		-		1			1							-		+						
	1	1	11		11	1						1	1.1	1.	1111							
				-	SUP	LEME	INTAL	REPORT	EXPECT	ED (14)						-	MONT	H DAY	YEAR			
									T						EXPECTED SUBMISSION							
YE	(If yes, co	omplete E	XPECTE	D SUBA	ISSION	DATE	5)		X	NO					DATE	15)		11	11			

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

ABSTRACT

At 0007 hours on May 5, 1985 Waterford 3 Steam Electric Station was at 17% reactor power when an uncomplicated reactor trip occurred as a result of an inadvertent closure of Main Steam Isolation Valve number 2. Because of a pressure transducer malfunction, coupled with the back leakage of oil through a check valve, oil pressure in the valve actuator decreased until the valve fully closed. The faulty components have since been repaired.

8506110711 850604 PDR ADOCK 0500038 D PDR NRC Form 366A (9-83)

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OM6 NO 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	PAGE (3)			
		YEAR	SEQUENTIAL REVISION NUMBER NUMBER				
Waterford 3 Steam Electric Station	0 5 0 0 3 8 3	2 8 5	- 0 1 7 - 0 0	0 2 OF 0 3			
TEXT (If more space is required, use additional NRC Form 386A's) (17)			the second second				

NARRATIVE

On May 4, 1985 Waterford 3 Steam Electric Station was at 17% reactor power when plant personnel observed that, contrary to its intended function, the motor driven hydraulic pumps for Main Steam Isolation Valve number 2 were constantly running. An investigation by Plant Personnel revealed that, due to a faulty hydraulic pressure transducer, the pumps were constantly cycling in an effort to compensate for the faulty pressure indication. The pressure transducer was subsequently repaired; however, at 2352 hours on May 4, 1985 Operations Personnel received an intermediate position indication for Main Steam Isolation Valve number 2. Plant Personnel investigated the problem and found that one of the motor driven hydraulic pumps had tripped on thermal overload (this was the result of the constant cycling of the pump described above) and, as a result of back leakage through the discharge check valve, was rotating backwards due to reverse flow from the operating motor driven hydraulic pump. Before the pump could be isolated oil pressure in the valve actuator decreased until, at 0006 hours on May 5. 1985, Main Steam Isolation Valve number 2 fully closed. Shortly thereafter, at 0007 hours, as a result of the valve closure, the Reactor Coolant System cold leg temperatures differed by greater than 18 degrees Fahrenheit precipitating an auxiliary trip in the Core Protection Calculator. This was signified as an uncomplicated reactor trip on low DNBR and high Local Power Density.

SAFETY CONSEQUENCES AND IMPLICATIONS

The above event resulted in an actuation of the Reactor Protective System during the initial Startup testing in which no primary systems parameters were exceeded. Since the Control Element Assemblies and the Reactor Protective System functioned as designed, and since Main Steam Isolation Valve number 2 failed in the safe condition, the event in no way placed Wateriord 3 in a degraded safety condition.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

US NUCLEAR REGULATORY COMMISSION APPROVED OMB NO 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)							LER NUMBER (6)								PAGE (3)					
										YE.	A.R.		SEQUENTIAL NUMBER		-	NUMBE	BER		Ι		
Waterford 3 Steam Electric Station	0	1	5	0	0	0	13	18	12	8	8 5	_	0	11	-	01	0	013 0	OF	0	13

CORRECTIVE ACTION

NRC Form 366A (9-83)

> The Main Steam Isolation Valve closed as a result of a malfunction of two components; namely, the hydraulic pressure transducer and the check valve on the discharge of the motor driven hydraulic pump. These components have since been repaired. Since environmental conditions (heat) may contribute to component failure, Station Modification Request 441 has been written to evaluate the possibility of moving several components located in the vicinity of the valve yoke.

SIMILAR EVENTS

NONE

PLANT CONTACT

O.D. Hayes, Operations. Superintendent, 504/464-3118



/ 142 DELARONDE STREET . P.O. BOX 8008 POWER & LIGHT / NEW ORLEANS LOUISIANA 70174-8008

. (504) 366-2345

June 4, 1985

W3P85-1404 A4.05

Director, Office of Nuclear Reactor Regulation ATTENTION: Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: Waterford 3 SES Docket No. 50-382 License No. NPF-38 Reporting of Licensee Event Report

Dear Sirs:

Attached is Licensee Event Report Number LER-85-017-00 for the Waterford 3 Steam Electric Station. This Licensee Event Report is submitted per 10CFR50.73(a)(2)(iv).

Very truly yours,

K.W. Cook Nuclear Support & Licensing Manager

KWC:GEW:sms

Attachment

cc: R.D. Martin, G.W. Knighton, D.M. Crutchfield, NRC Resident Inspectors Office, INPO Records Center (J.T. Wheelock), B.W. Churchill, W.M. Stevenson

IE22 1/1