

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER

VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

June 12, 1985


Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: McGuire Nuclear Station, Unit 1
Docket No. 50-369

Gentlemen:

On May 8, 1985, it was discovered that an operations group procedure did not specify to compensate hydrogen concentration in containment as given by the hydrogen analyzer due to temperature since the sample lines were not heat traced. This has been determined to be reportable with a report due June 7, 1985. Due to the extensive investigation, this date was not met. The investigation is continuing, and the report will be submitted by June 21, 1985. If you have questions, please contact Jerry Day at (704) 373-7033.

Very truly yours,



Hal B. Tucker

JBD/mjf

cc: Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

M&M Nuclear Consultants
1221 Avenue of the Americas
New York, New York 10020

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington Avenue
Farmington, CT 06032

8506180312 850612
PDR ADDCK 05000369
P PDR

A001
1/0