SAFEGUARDS INFURMATIO

DEC 3 0 1952

Docket No. 50-266 Docket No. 50-301

Wisconsin Electric Power Company ATTN: Robert E. Link Vice President Nuclear Power 231 West Michigan Street - P379 Milwaukee, WI 53201

Dear Mr. Link:

SUBJECT: PHYSICAL SECURITY AND MATERIAL CONTROL AND ACCOUNTABILITY INSPECTION AT POINT BEACH

This refers to the inspection conducted by Mr. T. J. Madeda of this office on November 30 - December 4, 1992. The inspection included a review of authorized activities for your Point Beach Nuclear facility. At the conclusion of this inspection, the findings were discussed with those members of your staff identified in the enclosed report.


Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, and interviews with personnel.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violations are of concern because weaknesses in your management oversight of the material control and accounting program resulted in the loss of a small amount of special nuclear material which was not identified in a timely manner.

Although 10 CFR 2.201 requires you to submit to this office, within 20 days of your receipt of this Notice, a written statement of explanation, we note that the violations have been corrected and the corrective actions were reviewed during this inspection. Therefore, no response with respect to this matter is required. However, we do request that you provide a written description of your analysis of completed corrective actions for a previous escorting violation to determine if any additional or different actions are required to prevent additional recurrence. You are requested to provide your response within 30 days of receipt of this report (see Section 2.a of Report Details). Your initial corrective actions for the violation identified in inspection reports 50-266/92017 and 50-301/92017 did not appear to have been completely effective.

EXEMPT FROM DISCLOSURE TO CFR 2.790 INFORMATION

ENCLOSURE CONTAINS LOCERS, 790 INFORMATION UPON SEPARATION TRIS FAUS IS DESCRITCHAED 9301060093 921230 PDR ADOCK 05000266 Q PDR



TEOY !

Enclosure Contains SAFEGUARDS INFORMATION Doon Separation This 1059 18 Decontrolled SAFEGUARDS INFURIMATION

Wisconsin Electric Power Company

DEC 3 0 1932 2

In addition, during this inspection, certain other of your activities appeared to be in violation of NRC requirements. However, as described in the enclosed inspection report (Section 6.a), you identified this violation. Therefore, the violation will not be subject to enforcement action because your efforts in identifying and correcting the violation meet the criteria specified in Section VII.B of the "General Statement of Policy and Procedures for NRC Enforcement Actions," (Enforcement Policy, 10 CFR Part 2, Appendix C).

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Part 73, Title 10, code of Federal Regulations. Section 73.21(c)(2). This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, our report of this inspection will not be placed in the NRC Public Document Room. In addition, areas examined during this inspection also concerns a subject matter which is exempt from disclosure according to Section 2.790 of the NRC's "Rules of Practice," Part 2, title 10, code of Federal Regulations. Consequently, the enclosure (Notice of Violation) to this letter and our report of this inspection will not be placed in the NRC Public Document Room.

The response requested by this letter is not subject to the clearance procedure of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by Cynthia D. Pederson" Cynthia D. Pederson, Chief Reactor Support Programs Branch

Enclosures:

1. Notice of Violation

(2.790(d) Information)

Inspection Reports

No. 50-266/92028(DRSS); No. 50-301/92028(DRSS)

(SAFEGUARDS INFORMATION)

See Attached Distribution

RIII

RIII

RIII

RIIL

Madeda/sd 12/ /92

Creed

Jackiw

EXEMPT FROM DISCLOSURE 10 CFR 2.790 MITORMATION Pederson

Enclosure Contains SAFEGUARDS TEORMATION Upon Separation This Page Is Decentrolled

BRIATEC ENCLOSUS INFORMATION 10CFR2 THIS THIS PAGE IN CHICAR STANDARD

SAFEGUARDS INFORMATIO

Wisconsin Electric Power Company 2 DEC 3 0 1992

In addition, during this inspection, certain other of your activities appeared to be in violation of NRC requirements. However, as described in the enclosed inspection report (Section 6.a), you identified this violation. Therefore, the violation will not be subject to enforcement action because your efforts in identifying and correcting the violation meet the criteria specified in Section V.A of the "General Statement of Policy and Procedures for NRC Enforcement Actions," (Enforcement Policy, 10 CFR Part 2, Appendix C).

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Part 73, Title 10, code of Federal Regulations, Section 73.21(c)(2). This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, our report of this inspection will not be placed in the NRC Public Document Room. In addition, areas examined during this inspection also concerns a subject matter which is exempt from disclosure according to Section 2.790 of the NRC's "Rules of Practice," Part 2, title 10, code of Federal Regulations. Consequently, the enclosure (Notice of Violation) to this letter and our report of this inspection will not be placed in the NRC Public Document Room.

The response requested by this letter is not subject to the clearance procedure of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Cynthia D. Pederson, Chief Reactor Support Programs Branch

Enclosures:

 Notice of Violation (2.790(d) Information)

2. Inspection Reports
 No. 50-266/92028(DRSS);
 No. 50-301/92028(DRSS)
(SAFEGUARDS INFORMATION)

See Attached Distribution

RILL
EXEMPT Madedaysdure
10 GFR 2 12/28/92 MATION

RIII Creed RIII RUP RIII

ENCLOSURE CONTAINS 10CFRE. 790 INFORMATION UPON SEPARATION THIS PAGE IS DESCRITCHED

SAFEGUARDS INFORMATE

Enclosure Contains SarEquards Information Upon Separation This Figu Is Decentrolled

Distribution

cc w/enclosures: G. J. Maxfield, Plant Manager NRR/DRIS/RSGB9D NMSS/HIGDON/4E4 OE Director

cc w/enclosures, w/o 2.790(d) and SAFEGUARDS INFORMATION:
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspector, RIII
Virgil Kanable, Chief
Boiler Section
Charles Thompson, Chairman
Wisconsin Public Service
Commission
Robert M. Thompson, Administrator
WI Div of Emergency Govt.

THE UP I TOM DISCHARGE

SAFEGUARDS INFORMATION

Encionure Contains SAPLAUARDS INFORMATION Upon Separation This Page Is Decontrolled