



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

JAN - 5 1993

Docket No. 50-382
License No. NPF-38

Entergy Operations, Inc.
ATTN: Ross P. Barkhurst, Vice President
Operations, Waterford
P.O. Box B
Killona, Louisiana 70066

Dear Mr. Barkhurst:

SUBJECT: 1993 NRC EROSION/CORROSION WORKSHOP

We would like to invite you and members of your staff to participate in the 1993 NRC Erosion/Corrosion (EC) Workshop. The workshop is scheduled to be held in Region I at the Valley Forge Sheraton Hotel and Convention Center on February 9, 1993. The objective of the workshop is to address current EC issues by promoting industry, NRC, and research organization discussions in regard to EC in high energy, carbon steel piping systems. The morning of the workshop is divided into a number of talks by industry, NRC, and EPRI members relative to the implementation of EC programs by industry licensees.

The afternoon of the workshop will allow participants to attend one of three discussion groups (breakout sessions). The breakout sessions cover the following areas relative to implementation of EC monitoring programs: A) EC monitoring program scopes, including methods for selecting systems and components for inspection; B) practices for inspecting carbon steel components; and C) methods of evaluating inspection data and dispositioning results. The discussion groups will present their findings to the collective workshop audience at the end of the breakout sessions. Final concluding remarks will be made by industry and NRC members at the end of the workshop program.

We request that you inform the Region I office of the estimated number of your staff who wish to attend the workshop at your earliest convenience after receipt of this letter, with an update of the number of participants provided by January 20, 1993. Also, please indicate the names of those attending the workshop and their personal preference for the afternoon discussion groups. A form is attached which may be used to ease your efforts. Please fax this form to Mr. Al Lohmeier at (215)337-5320 or call the information into him at (215)337-5089.

9301120094 930105
PDR ADOCK 05003382
P PDR

JEAS
1/1

Ross P. Barkhurst


-2-

A tentative schedule for the workshop on February 9, 1993, is attached. Registration for the workshop will take place between 8-8:30 a.m. The workshop will commence at 8:45 a.m.

The Sheraton is located at the corner of PA Rte. 363 and First Avenue in King of Prussia, PA. Rooms may be reserved in advance by calling the Sheraton at (215)337-2000. For those participants arriving by plane, limo service to and from the Philadelphia airport may be arranged by calling Liberty Airport Limo in King of Prussia at (215)688-6898, or at the airport at (215)365-8414. Taxi service in the King of Prussia area may be arranged by calling Norristown Yellow Cab at (215)277-1234, or Radnor Taxi at (215)688-6714.

A map of the Valley Forge - King of Prussia area is being attached for your convenience. The phone numbers of additional area hotels are listed on the map. Also attached are directions to the Sheraton Hotel from the Pennsylvania Turnpike, Interstate Rte. 76 (Schuylkill Expressway), and the Philadelphia Airport.

Should you have any questions or comments, please contact Mr. Ian Barnes of this office at (817)860-8176 or Mr. Al Lohmeier of Region I at (215)337-5089.


for Samuel J. Collins, Director
Division of Reactor Safety

Attachments: As stated

Ross P. Barkhurst

-3-

bcc/w attachments to DMB: IE45 - 50-382

bcc w/attachments:
DRP Section Chief
Resident Inspector
RIV Official File

bcc w/o attachments:
DRS Action Item File - AI 92-512
Barnes Reading File

RIV:TA:DRS *IB*
IBarnes:cs
1/5/93

see
D:DRS *ln*
SJCollins
1/5/93

110026

Ross P. Barkhurst

-3-

bcc/w attachments to DMB: IE45 - 50-382

bcc w/attachments:
DRP Section Chief
Resident Inspector
RIV Official File

bcc w/o attachments:
DRS Action Item File - AI 92-512
Barnes Reading File

RIV:TA:DRS *IB*
IBarnes:cs
1/5/93

DRS
D:DRS *fn*
SJCollins
1/5/93



UNITED STATES
NUCLEAR REGULATORY COMMISSION
 REGION I
 475 ALLENDALE ROAD
 KING OF PRUSSIA, PENNSYLVANIA 19406-1415

EROSION/CORROSION IN NUCLEAR POWER COMPONENTS AND PIPING

**1993 NRC EROSION/CORROSION WORKSHOP
 ATTENDANCE FORM**

Organization: _____

Number Attending: _____

Description of Breakout Discussion Sessions: A.,B.,C.

- A. Groups - Scope of Erosion/Corrosion Monitoring Programs, Including Methods of Selecting Systems and Components for Inspection
- B. Groups - Inspection Methods and Practices
- C. Groups - Methods of Evaluating Inspection Data to Assess the Acceptability of Inspected Components, and Corrective Actions

Names of Individuals Attending the Workshop, and Discussion Group Preferences:

<u>Name</u>	<u>First Preference</u>	<u>Alternate Preference</u>
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Please fax this form back to Al Lohmeier at (215) 337-5320, or call the information into him at (215) 337-5089, or return the form by mail by January 6, 1993 to:

Mr. Al Lohmeier
 NRC - Region I
 475 Allendale Rd
 King of Prussia, PA 19406



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
475 ALLENDALE ROAD
KING OF PRUSSIA, PENNSYLVANIA 19406-1415

EROSION/CORROSION IN NUCLEAR POWER COMPONENTS & PIPING

1993 NRC EROSION/CORROSION WORKSHOP
SCHEDULE OF EVENTS
Tuesday, February 9, 1993

8:00 - 8:30 AM	Registration in Lobby	
8:30 - 8:45 AM	Call to Assembly	A. Lohmeier
8:45 - 9:00 AM	Introduction	M. Hedges
9:00 - 9:15 AM	Welcome	T. Martin
9:15 - 10:00 AM	E/C Monitoring Program NRC Overview	W. Russell
10:00 - 10:15 AM	Break	All
10:15 - 11:00 AM	E/C Monitoring Program Utility Overviews	S. Miltenberger
11:00 - 11:45 AM	E/C Monitoring Program EPRI Overview	B. Chexal
11:45 - NOON	Questions	All
NOON - 1:00PM	LUNCH	All
1:00 - 1:15 PM	Formation of Break out Groups	A. Lohmeier

EROSION/CORROSION IN NUCLEAR POWER COMPONENTS & PIPING

1993 NRC EROSION/CORROSION WORKSHOP
SCHEDULE OF EVENTS
Tuesday, February 9, 1993

1:15 - 2:45 PM	Breakout Sessions	A,B,C
	A. Scope of Erosion/Corrosion Monitoring Programs, Including Methods of Selecting Systems and Components for Inspection	
	B. Inspection Methods and Practices	
	C. Methods of Evaluating Inspection Data to Assess the Acceptability of Inspected Components and Corrective Actions	
2:45 - 3:00 PM	Break	All
3:00 - 3:15 PM	Summary & Feedback Breakout Session A. Groups	A Facilitator
3:15 - 3:30 PM	Summary & Feedback Breakout Session B. Groups	B Facilitator
3:30 - 3:45 PM	Summary & Feedback Breakout Session C. Groups	C Facilitator
3:45 - 4:00 PM	Concluding Observations	S. Miltenberger
4:00 - 4:15 PM	Concluding Observations	J. Durr
4:15 - 4:30 PM	Closing Remarks	M. Hodges
4:30 PM	Adjournment	A. Lohmeier



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
475 ALLENDALE ROAD
KING OF PRUSSIA, PENNSYLVANIA 19408-1415

ATTACHMENT
PAGE 4 of 5

1993 NRC EROSION/CORROSION WORKSHOP
TUESDAY, FEBRUARY 9, 1993

Directions to the Valley Forge Sheraton Hotel
and Convention Center


From the Pennsylvania Turnpike:

1. Turnpike east: Take the Pennsylvania Turnpike (I-76) east to Exit No. 24, the Valley Forge Exit. Take the first right immediately after the toll booth, for PA Rte. 363. Follow Rte. 363 north (go under the Turnpike) until you hit First Avenue. The Sheraton will be on the corner.
2. Turnpike west: Take the Pennsylvania Turnpike (I-276) west to Exit No. 24, the Valley Forge Exit. Follow the instructions, above, for Turnpike East until you reach the Sheraton.

NOTE: The Pennsylvania Turnpike is I-76 west of Exit No. 24, and I-276 east of Exit No. 24.

From the Schuylkill Expressway (I-76 west) and from the Philadelphia Airport:

1. Schuylkill Expressway, I-76 west: Follow the Schuylkill Expressway (I-76) to Exit No. 26N, for U.S. Rte. 202, north. Get into the farthest left lane after exiting onto Rte. 202, north, and make a left hand turn onto Gulph Mills Road (PA Rte. 363). Take Rte. 363 north until you reach the Sheraton on the corner of First Avenue: Rte 363 will proceed past the King of Prussia Plaza, under the Expressway, past the Stouffers Restaurant, under the Pennsylvania Turnpike, and on up to the Sheraton.
2. Philadelphia Airport: Follow the airport signs until you reach I-95, south. Proceed south on I-95 until you reach the Blue Route, I-476. Follow I-476 north (signs will say to Plymouth Meeting) until you get to Exit 6B for I-76, west. Exit onto I-76, going west to King of Prussia. Follow the directions above for Schuylkill Expressway, I-76 west, to get to the Sheraton.



Hotels
(Area Code 215)

Budget	337-2000
Hilton	337-1800
Holiday Inn	962-8111
Howard Johnson's	265-7200
Comfort Inn	265-1300
	265-7500
	265-4500
	962-0700

Sheraton	337-2000
Stouffer's	337-1800
Hampton Inn	962-8111
Harriott Courtyard	687-6700

Liberty Airport Limos:	King of Prussia	688-6898
Taxi Service:	Phila. Int'l Airport	365-8414
	Horriestown Radio	539-1700
	Horriestown Yellow	277-1234
	Hadnor Taxi	688-6714