

ENCLOSURE 1

NOTICE OF VIOLATION

Mississippi Power and Light Company  
Grand Gulf

Docket No. 50-416  
License No. NPF-29

The following violations were identified during an inspection conducted on March 16 - April 11, 1985. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

1. 10 CFR 50, Appendix B, criterion VI states in part that measures shall be established to assure that documents, including changes, are reviewed for adequacy and approved for release by authorized personnel.

Contrary to the above, procedure 06-EL-1L21-0-0001 was inadequate in that it permitted an Engineered Safety Feature (ESF) actuation when technicians put the Division 2 batteries on equalize charge.

This is a Severity Level IV violation.

2. Technical Specification 6.8.1 requires that written procedures shall be established, implemented and maintained.

Contrary to the above, on April 4, 1985, steps in Surveillance Procedure 06-EL-1E31-M-0001 were performed out of sequence resulting in an ESF containment isolation valve actuation. This ESF actuation caused isolation of the Reactor Core Isolation Cooling System.

This is a Severity Level IV violation.

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: APR 25 1985

8505200303 850425  
PDR ADOCK 05000416  
G PDR