

Cambridge Muclear Corporation

575 MIDDLESEX TURNPIKE, BILLERICA, MASSACHUSETTS DIS21 - PHONE 935-4050 AREA CODE 617

September 11, 1970

Mr. Robert E. Brinkman Materials Branch Division of Materials Licensing U. S. Atomic Energy Commission Washington, D. C. 20545

Dear Mr. Brinkman:

With respect to your letter dated July 17, 1970, the following items are confirmed:

- Confirmation is made that we are reques ing termination of license 20-06799-01.
- We do confirm that there is no more radioactive material in inventory at 131 Portland Street, Cambridge, Massachusetts; either as product or packaged wastes.
- We do confirm that smear survey results are in units of dnm/100 cm² as required in your letter of October 7, 1969.
- 4. We do confirm that radiation level surveys were made with equipment having a window thickness of 1.4 to 2.8 milligrams per cm² as required in your letter of October 7, 1969.
- 5. Confirmation is made that alpha surveys were made by Robert U. Johnson. Enclosed is a copy of the results of the survey.
- 6. Confirmation is made that the further decontamination recommended in Mr. Robert U. Johnson's letter of June 3, 1970 was carried out and the results were included in our letter to you dated July 3, 1970 which was dictated by Mr. M. W. Milgemeier prior to his termination as Radiation Safety Officer.

Sincerely,

Robert C. Ferris Q.
Vice President

RCF/rc

Inc.

CADIES
TO COMPLIANCE


0/103

Kr. Robert Ferris Cambridge Nuclear Co. 575 Middlesex Turnpike, Billerica, Mass. 01821

Dear Mr. Ferris:

A survey made this morning at the 131 Portland Street location indicated the following alphas in disintegrations/minute/100 cm2;

	LOCATION	NESULT
11.Y11	Wall at 36" above floor	7
#BII	Wall at 6" above floor **	8
13 C 11	Wall at 36" above floor	6
" Di	Belt motor	6
n Du	Floor(previously above limits) ***	37 ***
$_{11}\lambda _{cH}$	Floor 24" beyond area "E"	86
пQн	Wall at 6" above floor	10
n Hn	Floor between new flooring & motor	4



* * After 2nd washing ** Average of two wipes

Yours truly,

Robert U. Johnson