



Commonwealth Edison
1400 Opus Place
Downers Grove, Illinois 60515

January 14, 1993

Dr. Thomas E. Murley, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Attn: Document Control Desk

Subject: Braidwood Station Unit 1
Inservice Inspection Report for
Interval 1, Period 2, Refuel Outage 1
NRC Docket Nos. 50-456

Reference:(a) December 15, 1988, S.C. Hunsader to letter
to T. E. Murley

Dear Dr. Murley:

Reference (a) provided the complete Braidwood Station Units 1 and 2 Inservice Inspection (ISI) program for NRC review that is currently being implemented at the station. In accordance with the requirements of this program and Article IWA-6000 of Section XI of the ASME Boiler and Pressure Vessel Code (1983 Edition through and including the Summer, 1983 Addenda) Commonwealth Edison is submitting the report of the ISI performed at Unit 1 from May 19, 1991 through November 3, 1992. This report is required to be submitted within 90 days of the completion of a refueling outage. The Unit 1 refueling outage was completed on November 3, 1992.

Please address any questions regarding this submittal to this office.

Very truly yours,

T.W. Simpkin
Nuclear Licensing Administrator

190024

cc: J. Hickman - NRR w/o attachment
B. Clayton - RIII w/o attachment
Braidwood Resident Inspector w/o attachment

ZNLD/968/8

9301210195 930114
PDR ADOCK 05000456
G PDR

ADH