

NORTHERN STATES POWER COMPANY
Monticello, Minnesota 55362

May 19, 1973

Mr. Boyce H. Grier, Director
Directorate of Regulatory Operations
Region III
United States Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 61037

Dear Mr. Grier:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

On May 18, 1973, the High Pressure Coolant Injection System (HPCI) isolated on high steam flow during a "quick start" full flow surveillance test. Investigation is in progress.

Yours very truly,


C E Larson
Plant Manager
NORTHERN STATES POWER COMPANY

CEL/lck

cc: Mr. J. F. O'Leary, Directorate of Licensing
File

9211160603 730519
PDR ADOCK 05000263
S PDR

3 21-73 7 10:55am
C E Larson



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 856-2660

REGULATORY OPERATIONS, REGION III

10-263

A. RO Inspection Report No. _____

Transmittal Date : _____

Distribution:

RO Chief, RT&OB or RO Chief, RCB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)

Distribution:

RO Chief, M&FFB
RO:HQ (4)
L:D/D for Fuel & Materials
DR Central Files

B. RO Inquiry Report No. _____

Transmittal Date : _____

Distribution:

RO Chief, RT&OB or RO Chief, RCB (2)
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)

Distribution:

RO Chief, M&FFB
RO:HQ
DR Central Files

C. Incident Notification From: Northern States Power Co. DPR-22
(Licensee & Docket No. (or License No.))

Transmittal Date : May 23, 1973

Distribution:

RO Chief, RT&OB or RO Chief, RCB
RO:HQ (4)
Licensing (4)
DR Central Files

Distribution:

RO Chief, M&FFB
RO:HQ (4)
L:D/D for Fuel & Materials
DR Central Files

Abnormal
cc.