

May 4, 1972

PDR

Docket No. 50-263

Dr. Chester P. Siess  
Chairman, Advisory Committee  
on Reactor Safeguards  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Dr. Siess:

copies of the following are transmitted for the

~~Commission~~ (16)

information.

Letter from Northern States Power Company dated April 25, 1972, reporting three occurrences at the Monticello Nuclear Generating Plant concerning improper functioning of the KHR service water regulating valve control, malfunction of the containment isolation valve, and failure of the HPCI steamline high area temperature switch to trip.

Sincerely,

*Donald J. Skovholt*  
Donald J. Skovholt  
Assistant Director  
for Reactor Operations  
Division of Reactor Licensing

Distribution  
~~Docket File~~  
Branch Reading

Enclosures:  
As stated

OFFICE ▶	DL <i>MDP</i>						
SURNAME ▶	RMDiggs:sjh						<i>LB</i>
DATE ▶	5/4/72						

Form AEC-318 (Rev. 9-53) AECM 0240

U. S. GOVERNMENT PRINTING OFFICE : 1970 O - 405-340

9211200356 720504  
PDR ADOCK 05000263  
O PDR