

UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

January 23, 1975

OFFICE OF THE CHAIRMAN


50-203

NRC PDR

Lee V. Gossick
Acting Executive Director for Operations

CRACKS IN FOUR-INCH BYPASS LINES

With the discovery of the crack at Monticello, and the fact that the NRC has not had a review of the situation in this and other GE plants, I would like a Commission briefing on the matter as soon as possible. Please include the history and latest assessment of the cause and your recommendations for future action.



William A. Anders



DR-1071

Stated
AK

9211230340 750123
PDR ADOCK 05000263
P PDR