

NSP

NORTHHERN STATES POWER COMPANY

Naticello Nuclear Generating Plant
Naticello, Minnesota 55952

August 27, 1975


Mr. J. G. Koppler, Director
Region III
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Koppler:

NATICELLO NUCLEAR GENERATING PLANT
Docket No. 50-265 License No. DPR-22

On August 26, 1975, it was discovered that the control circuit for valve MD-2075, Steam Supply to HPCI Turbine, was de-energized. An investigation revealed that the motor control unit undervoltage relay coil had opened. The coil was replaced and remote operability of the valve was demonstrated. Further investigation of this occurrence is continuing.

Yours very truly,



G. H. Landon
Plant Manager
Naticello Nuclear Generating Plant

CEL/hwa

cc: A. Giambusso
G. Charnoff
Minnesota Pollution Control Agency
Attn: J. W. Ferman
File

Copies telecopied to Koppler and Giambusso.

9211230452 750827
PDR ADOCK 05000263
S PDR

202 4 26 8/27/75 ju