



*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92674-0128

R. W. KRIEGER  
STATION MANAGER

November 19, 1992

TELEPHONE  
(714) 268-6255

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Docket Nos. 50-361 and 50-362  
30-Day Report  
Licensee Event Report No. 92-009, Revision 1  
San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter, R. W. Krieger (SCE) to USNRC Document Control Desk, dated  
July 14, 1992

The referenced letter provided Licensee Event Report (LER) No. 92-009, Revision 0, for an occurrence involving the mis-alignment of a salt water cooling pump emergency seal water supply isolation valve. Since this occurrence involves similar systems, cause, and corrective actions applicable to Units 2 and 3, a single report for Unit 2 is being submitted in accordance with NUREG-1022. Neither the health nor the safety of plant personnel or the public was affected by this occurrence.

If you require any additional information, please so advise.

Sincerely,

Enclosure: LER No. 92-009, Rev. 1

cc: C. W. Caldwell (USNRC Senior Resident Inspector, Units 1, 2 and 3)

J. B. Martin (Regional Administrator, USNRC Region V)

Institute of Nuclear Power Operations (INPO)

230008

9211240051 921119  
PDR ADOCK 05000361  
S PDR

IF22  
11